

Serial	PR No.	Document Date	Item Code	PR Line Description	PR Qty	Unit	Buyer	Buyer site	EMAIL ADDRESS	PR Status	RFQ Closing Dated
1	11505568	22-Jul-2015	SER0000027	REPAIR TONG STRUCTURE 107186(MMDD004541) FOR KRESS	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
2	11505569	22-Jul-2015	SER0000027	REPAIR VERTICAL CENTRIFUGAL PUMPV005 VAB351/1SA (S/N.VEP5-05)	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
3	11505570	24-Jul-2015	SER0000027	REPAIR TOP BUR CHOCKS F4-F7NO.9 -ซ่อมรูลิ้น	1.00	Each	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
4	11505572	22-Jul-2015	SER0000027	REPAIR DESCALING VALVE 4" 2-WAY MOD.4108A P/N 97933941 (S/N.6/9) [NEED CHECK SHEET INSP.]	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
5	11505573	22-Jul-2015	SER0000027	REPAIR PREFILLING VALVE TYPE 2-VDS-08-V6 NP315(S/N.2/11) [NEED CHECK SHEET INSP]	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
6	11505574	22-Jul-2015	SER0000027	REPAIR WRAPPER ROLL COMPLETE SET G05700 [เปลี่ยนเฉพาะ ROLLER]	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
7	11505575	22-Jul-2015	SER0000027	REPAIR LEFT GUIDE DWG.G05441.POS.58(G04039) (NO.L1) FIM.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
8	11505575	22-Jul-2015	SER0000027	REPAIR LEFT GUIDE DWG.G05441.POS.58(G04039) (NO.L2) FIM.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
9	11505576	22-Jul-2015	SER0000027	REPAIR RIGHT GUIDE DWG.G05441 POS.59 (G04773) [NO.R1] FIM.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
10	11505576	22-Jul-2015	SER0000027	REPAIR RIGHT GUIDE DWG.G05441 POS.59 (G04773) [NO.R2] FIM.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
11	11505591	22-Jul-2015	SER0000027	REPAIR HYD. PUMP "PARKER" MODEL P350 B289417 P/N.323 9120 303(NO.15) FOR FANTUZZI NO.12-17	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
12	11505592	22-Jul-2015	SER0000027	REPAIR DOUBLE HYD.PUMP#GEAR PUMPMOD.P350 B497SPL AB 15-25 (NO.10) FOR :FANTUZZI 1-10	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
13	11505592	22-Jul-2015	SER0000027	REPAIR DOUBLE HYD.PUMP#GEAR PUMPMOD.P350 B497SPL AB 15-25 (NO.11) FOR :FANTUZZI 1-10	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
14	11505593	22-Jul-2015	SER0000027	REPAIR DOUBLE HYD.PUMP#GEAR PUMPMOD.P350 B497SPL AB 15-25 (NO.12) FOR :FANTUZZI 1-10	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
15	11505593	22-Jul-2015	SER0000027	REPAIR DOUBLE HYD.PUMP#GEAR PUMPMOD.P350 B497SPL AB 15-25 (NO.13) FOR :FANTUZZI 1-10	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
16	11505594	22-Jul-2015	SER0000027	REPAIR HYD.CYL.PARKER 4BB-2H LR 14M 16"FOR HOLD DOWN ROLL PO-LINE.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
17	11505595	22-Jul-2015	SER0000027	REPAIR HOLD DOWN ROLL COMPONENT:520809 FOR RECOILER PPPL	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
18	11505597	22-Jul-2015	SER0000027	REPAIR HYD.CYL PARKER 5J2H-LR34M 12" FOR CROP SHEAR PO-LINE.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
19	11505601	22-Jul-2015	SER0000027	REPAIR HYD.CYL PARKER 3.25BB2H-L R 19M6"(CARRYOVER TABLE) PO-LINE.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
20	11505603	22-Jul-2015	SER0000027	REPAIR HYD.CYL.1000-10406 M.74599 (FOSSA) (NO.1) FOR CHOCKS LIFTING FRAME BALANCING STAND SKM#1,2	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
21	11505603	22-Jul-2015	SER0000027	REPAIR HYD.CYL.1000-10406 M.74599 (FOSSA) (NO.2) FOR CHOCKS LIFTING FRAME BALANCING STAND SKM#1,2	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
22	11505604	22-Jul-2015	SER0000027	REPAIR HYD.CYL."FOSSA" TYPE 1000-10394 FOR PAY OFF SKM#1,2	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
23	11505605	22-Jul-2015	SER0000027	REPAIR HYD.CYL.1000-10411 DWG.M74823 FOR UPPER EXIT TABLE UP-DOWN SKM#1,2	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15
24	11505606	22-Jul-2015	SER0000027	REPAIR HYD.CYL."REXROTH" CGT3 MT4200/90/1015 F11 HUM FOR PAY OFF SKM#3	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	3-Aug-15

PR Received dated 20 Jul 2015-26 Jul 2015

Services & Others

Post Dated 27 Jul 2015

Serial	PR No.	Document Date	Item Code	PR Line Description	PR Qty	Unit	Buyer	Buyer site	EMAIL ADDRESS	PR Status	RFQ Closing Dated
52	11505589	22-Jul-2015	SER0000027	REPAIR STARTER MOTOR 24V S/N02J05 P/N3938502 (NO.5)FOR ENGINE CUMMIN	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	3-Aug-15
53	11505590	22-Jul-2015	SER0000027	REPAIR ALTERNATOR 24V. 100AM. (MITSUBISHI) P/N.ME160917 A4T95099 (NO.10) FOR FANTUZZI	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	3-Aug-15
54	11505590	22-Jul-2015	SER0000027	REPAIR ALTERNATOR 24V. 100AM. (MITSUBISHI) P/N.ME160917 A4T95099 (NO.11) FOR FANTUZZI	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	3-Aug-15
55	11505612	22-Jul-2015	SER0000027	REPAIR ALTERNATOR GR-CHARGING P/N.100-5047 FOR KRESS (NO.6)	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	3-Aug-15
56	11505612	22-Jul-2015	SER0000027	REPAIR ALTERNATOR GR-CHARGING P/N.100-5047 FOR KRESS (NO.7)	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	3-Aug-15
57	11505612	22-Jul-2015	SER0000027	REPAIR ALTERNATOR GR-CHARGING P/N.100-5047 FOR KRESS (NO.8)	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	3-Aug-15
58	11505375	21-Jul-2015	SER0000024	ซื้อเสา access point ทดแทนเสาที่เสียหาย	1.00	JOB	MR. SIRICHAJ PROMCHAN	BKK	SirichaiPr@ssi-steel.com	INCOMPLETE	3-Aug-15
59	11505378	21-Jul-2015	SER0000024	ซ่อม Printer PM4i S/N : 14920120158 A/C : 5000301166 อาการเสีย : สั่ง Print แล้วไม่มีตัวหนังสือออกมา	1.00	Each	MR. SIRICHAJ PROMCHAN	BKK	SirichaiPr@ssi-steel.com	INCOMPLETE	3-Aug-15
60	11503705	24-Jul-2015	SER0000030	Repair X-RAY GENERATOR 100kV/640W (RFAZZ37802) (Supplier IMS Messsysteme GmbH)	1.00	Each	MR. TANAPOL PHETPHO	BKK	tanapolp@ssi-steel.com	INCOMPLETE	3-Aug-15