

PR Received dated 2 Nov 2015 - 8 Nov 2015

Services & Others

Post Dated 9 Nov 2015

Serial	PR No.	Document Date	Item Code	PR Line Description	PR Qty	Unit	Buyer	Buyer site	EMAIL ADDRESS	PR Status	RFQ Closing Dated
1	11509012	4-Nov-2015	SER0000027	ร่าจ่าง M/C ROLL TABLE COIL CUTTING (2 EA)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	16-Nov-2015
2	11509020	5-Nov-2015	SER0000027	REPAIR LIFTING CYLINDER P/N 2144.831526 (LENGTH2140MM) [NO.4] USE FOR FANTUZZI	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	16-Nov-2015
3	11509020	5-Nov-2015	SER0000027	REPAIR LIFTING CYLINDER P/N 2144.831526 (LENGTH2140MM) [NO.30] USE FOR FANTUZZI	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	16-Nov-2015
4	11509023	5-Nov-2015	SER0000027	ร่าจ่างค้ดค่นกัซซัซนงาน BINARY G05428 POS18 (G07653 REV.B)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	16-Nov-2015
5	11509052	7-Nov-2015	SER0000027	ร่าจ่างซ้อมRECIRCULATING PUMP TYPE.KFUG42+80 "S.I.D. STEIBLE" (DWG.A05005P1000SHEET 15 POS.28) FOR FUEL OIL SYSTEM FURNACE 1,2	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	16-Nov-2015
6	11509053	7-Nov-2015	SER0000027	OVERHAUL COMBUSTION CONTROL VALVE DN 500 FOR FUR#1 ZONE 6.	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	16-Nov-2015
7	11509068	7-Nov-2015	SER0000027	REPAIR HYD.CYL PARKER 5J2H-LR34M 12" FOR CROP SHEAR PO-LINE.	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	16-Nov-2015
8	11509069	7-Nov-2015	SER0000027	REPAIR DESCALING VALVE 4" 2-WAY MOD.4108A P/N 97933941 (S/N.1/9) [NEED CHECK SHEET INSP.]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	16-Nov-2015
9	11509070	7-Nov-2015	SER0000027	REPAIR PNEUMATIC CYL.2000-4258 (G08006) COMPLETE SET (ENTRY/OS) COB.	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	16-Nov-2015
10	11509070	7-Nov-2015	SER0000027	REPAIR PNEUMATIC CYL.2000-4258 (G08006) COMPLETE SET (EXIT/OS) COB.	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	16-Nov-2015
11	11509075	7-Nov-2015	SER0000027	REPAIR ROLLER TABLE FOR COIL CUTTING (CYS.) [NO.1]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	16-Nov-2015
12	11509075	7-Nov-2015	SER0000027	REPAIR ROLLER TABLE FOR COIL CUTTING (CYS.) [NO.2]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	16-Nov-2015
13	11509029	7-Nov-2015	SER0000013	ค้ร่วลซ้อมค้ดค่นร่าจ่าง	1.00	JOB	TEANGTUNG, MRS. CHUTIPA	BSP	Chutipat@ssi-steel.com	INCOMPLETE	16-Nov-2015
14	11508967	7-Nov-2015	SER0000028	REWIND MOTOR AC. 380V 55/63KW 1480/1780RPM MBT250M4(B3)	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	16-Nov-2015
15	11509026	5-Nov-2015	SER0000028	OVERHAUL MOTOR AC. 40-380V 3.7KW 100-1075RPM B4R160M6 (B3)	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	16-Nov-2015
16	11509036	5-Nov-2015	SER0000028	REWIND MOTOR GEAR 380V 0.37 KW 1500RPM G80F/D71B34	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	16-Nov-2015
17	11509037	7-Nov-2015	SER0000028	CHANGE PT100 AND INSPECTION MOTOR 250 KW 1482RPM TYPE IY355L-4 380V 50 HZ FOR AIR COM No.4,8,9,10	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	16-Nov-2015
18	11509038	5-Nov-2015	SER0000029	REPAIR CARD DINTA Sr.no.9221277 FOR WO.No.459115 LAB WCE	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	16-Nov-2015
19	11509039	5-Nov-2015	SER0000029	REPAIR CARD EXCITER 380VAC/300VDC ELC25908819 Sr.no.WCE0049 FOR WO.No.456454 LAB WCE	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	16-Nov-2015
20	11509041	5-Nov-2015	SER0000029	REPAIR CARD EXCITER 380VAC/300VDC CODE ELC25908819 FOR WO.No.454262 LAB WCE	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	16-Nov-2015
21	11509042	5-Nov-2015	SER0000029	REPAIR CARD POWER SUPPLY 115/24V 20A FOR FIM FOR WO.No.437457 LAB WCE	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	16-Nov-2015
22	11509045	6-Nov-2015	SER0000029	REPAIR CARD PR50A Sr.no.AS92061-2 FOR WO.No.449603 LAB WCE	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	16-Nov-2015
23	11509046	6-Nov-2015	SER0000029	REPAIR CARD CONTROL CONDBE 1 EA Sr.no.620406M232 FOR WO.No.449607 LAB WCE	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	16-Nov-2015
24	11509049	5-Nov-2015	SER0000029	REPAIR POWER SUPPLY 250W 24V 10A MODEL BPUDA FOR WO.No.461256 LAB WCE	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	16-Nov-2015
25	11509013	5-Nov-2015	SER0000013	ซ้อม PNEUMATIC SEALER MODEL: PS21	1.00	JOB	ONCHAWIANG, MR. PHAIBOON	BSP	PhaiboonO@ssi-steel.com	INCOMPLETE	16-Nov-2015
26	11509027	5-Nov-2015	SER0000013	ร่าจ่างท่ากลอ้งลัศค้ดค่นจ่า isolation lock	8.00	Each	ONCHAWIANG, MR. PHAIBOON	BSP	PhaiboonO@ssi-steel.com	INCOMPLETE	16-Nov-2015

PR Received dated 2 Nov 2015 - 8 Nov 2015

Services & Others

Post Dated 9 Nov 2015

Serial	PR No.	Document Date	Item Code	PR Line Description	PR Qty	Unit	Buyer	Buyer site	EMAIL ADDRESS	PR Status	RFQ Closing Dated
27	11509019	5-Nov-2015	SER0000027	REPAIR ALTERNATOR 24V. 100AM. (MITSUBISHI) P/N.ME160917 A4T95099 [NO.1] FOR FANTUZZI	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	16-Nov-2015
28	11509021	5-Nov-2015	SER0000027	ว่าจ้างย้ายสายไฮดรอลิคสกรู Mobile crane TADANO No.1	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	16-Nov-2015
29	11508066	5-Nov-2015	SER0000028	ว่าจ้างจัดทำ BOLT สำหรับ HSCB	1.00	JOB	SRIYA, MR. VARIN	BSP	varinsr@ssi-steel.com	INCOMPLETE	16-Nov-2015