

| Serial | PR No. | Document Date | Item Code | PR Line Description | PR Qty | Unit | Buyer | Buyer site | EMAIL ADDRESS | PR Status | RFQ Closing Dated |
|--------|----------|---------------|------------|---|--------|------|------------------------|------------|--|------------|-------------------|
| 1 | 11504177 | 24-Jun-2015 | SER0000027 | ว้จ้จ้จ้จ้ Heat plate Furnace 3 No 2 | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 2 | 11504223 | 22-Jun-2015 | SER0000027 | REPAIR HEAT EXCHANGER TYPE BEM 806-21-4 For Cooling H5 [S/N.28532] | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 3 | 11504324 | 24-Jun-2015 | SER0000027 | REPAIR SCREW JACK FOR PASS LINE ADJUSTMENT OF FOUR HIGH SKIN PASS#3. | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 4 | 11504325 | 22-Jun-2015 | SER0000027 | REPAIR HYD.CYL.1000-15953 "FOSSA" G53903 (220/140/950) EXCLUDE TRANSDUCER (NO.4) [NEED CHECK SHEET INSP.] | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 5 | 11504326 | 22-Jun-2015 | SER0000027 | REPAIR BALANCING BLOCK ENTRY O/S605526 POS.3-25 (NO.2)[NEED CHECK SHEET INSP.] | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 6 | 11504327 | 22-Jun-2015 | SER0000027 | REPAIR HYD.CYL.FOR CHARGING&DISCHARGE(H11)B125 R80 S2180 mm. FUR#3(NO.1)[NEED CHECK SHEET INSP.] | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 7 | 11504330 | 22-Jun-2015 | SER0000027 | REPAIR DRIVING SHAFT DWG.A/74452 (PAY OFF GEAR) COMPLETE SET FOR PAY OFF SKM#1,2 | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 8 | 11504487 | 30-Jun-2015 | SER0000027 | ว้จ้จ้จ้จ้ Shim Crop Shear | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 9 | 11504634 | 30-Jun-2015 | SER0000027 | REPAIR SINGLE ROW STITCHER COMPLETE SET FOR PO-LINE. | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 10 | 11504638 | 1-Jul-2015 | SER0000027 | REPAIR WRAPPER ROLL COMPLETE SET G05700 (SEE DETAIL) [WR1/DC1] (NEED CHECK SHEET INSP) | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 11 | 11504639 | 1-Jul-2015 | SER0000027 | REPAIR WRAPPER ROLL COMPLETE SET G05700 (SEE DETAIL) [WR3/DC2] (NEED CHECK SHEET INSP) | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 12 | 11504642 | 1-Jul-2015 | SER0000027 | REPAIR TRANSFER CARS ASS Y G05726 2/2 (DC.2) | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 13 | 11504643 | 3-Jul-2015 | SER0000027 | REPAIR OIL PURIFIER MODEL.HVAC 12453850 C8 SN (SL0357)"PALL" | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 14 | 11504644 | 3-Jul-2015 | SER0000027 | REPAIR HEAT EXCHANGERS L=3140MM TYPE BEM610-238A-2 DWG.W27238 FOR STATION H1 (S/N.28956) | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 15 | 11504649 | 1-Jul-2015 | SER0000027 | REPAIR BOTTOM PULLEY + BEARING DWG.0104006 OF MAIN ROPE FOR OHC# 13,14(NO.1) | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 16 | 11504649 | 1-Jul-2015 | SER0000027 | REPAIR BOTTOM PULLEY + BEARING DWG.0104006 OF MAIN ROPE FOR OHC# 13,14(NO.2) | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 17 | 11504652 | 1-Jul-2015 | SER0000027 | REPAIR TOP ENTRY PINCH ROLL COMPLETE SET DWG.15037002 FOR SHL | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 18 | 11504654 | 1-Jul-2015 | SER0000027 | REPAIR HYD.CYL HC2A-80/36x120 DIA.80/36x120+MOUNTING"A" WITH RACK FOR CORRECTING ROLL SHL | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 19 | 11504656 | 1-Jul-2015 | SER0000027 | REPAIR STEERING CYLINDER P/N 243070 (NO.13) FOR FANTUZZI | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 20 | 11504659 | 1-Jul-2015 | SER0000027 | REPAIR STEERING ROD P/N.AE4.253015 (MMDDD004811)+ BUSH P/N.C17.253003 FOR ORMIG CRANE (NO.1) | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 21 | 11504659 | 1-Jul-2015 | SER0000027 | REPAIR STEERING ROD P/N.AE4.253015 (MMDDD004811)+ BUSH P/N.C17.253003 FOR ORMIG CRANE (NO.2) | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 22 | 11504660 | 1-Jul-2015 | SER0000027 | REPAIR ARM STEERING P/N AE4.243044 (MMDDD004307) (MMDDD003040) FOR REAR AXLE OF FANTUZZI(NO.10) | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 23 | 11504660 | 1-Jul-2015 | SER0000027 | REPAIR ARM STEERING P/N AE4.243044 (MMDDD004307) (MMDDD003040) FOR REAR AXLE OF FANTUZZI(NO.39) | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |

| Serial | PR No. | Document Date | Item Code | PR Line Description | PR Qty | Unit | Buyer | Buyer site | EMAIL ADDRESS | PR Status | RFQ Closing Dated |
|--------|----------|---------------|------------|---|--------|---------------|---------------------------|------------|--|------------|-------------------|
| 24 | 11504661 | 1-Jul-2015 | SER0000027 | REPAIR CYLINDER ARM P/N AE4.243035 (LEFT SIDE) MMDDD004331 (NO.1) FOR STEERING OF FANTUZZI | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 25 | 11504661 | 1-Jul-2015 | SER0000027 | REPAIR CYLINDER ARM P/N AE4.243035 (LEFT SIDE) MMDDD004331 (NO.11) FOR STEERING OF FANTUZZI | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 26 | 11504661 | 1-Jul-2015 | SER0000027 | REPAIR CYLINDER ARM P/N AE4.243035 (LEFT SIDE) MMDDD004331 (NO.20) FOR STEERING OF FANTUZZI | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 27 | 11504665 | 1-Jul-2015 | SER0000027 | REPAIR HYD.CYL.1000-10406 M.74599 (FOSSA) FOR CHOCKS LIFTING FRAME BALANCING STAND SKM #1,2 | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 28 | 11504800 | 3-Jul-2015 | SER0000027 | ว่าจ้างซ่อม PUMP GREASE "AROEXTRUSION PUMP RATIO 65:1 (MODEL NPC37R I6-J3D)" FOR AREA RM-CB. | 1.00 | JOB | MR. AEK SIRIMUANGKHALA | BSP | AekS@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 29 | 11504234 | 22-Jun-2015 | SER0000017 | ว่าจ้างเปิดผนังติดกันสาดบริเวณ indoor coil yard จำนวน 4 ชุด | 1.00 | JOB | MRS. ANCHALEE PIKKANESUAN | BSP | AnchaleeJ@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 30 | 11504578 | 29-Jun-2015 | SER0000027 | ว่าจ้างรื้อติดตั้งวัสดุทนไฟและติดตั้งหมวมเตย | 1.00 | JOB | MRS. ANCHALEE PIKKANESUAN | BSP | AnchaleeJ@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 31 | 11504264 | 22-Jun-2015 | SER0000034 | ค่ากำจัด sludge from PO | 200.00 | Metric Tonnes | MRS. CHUTIPA TEANGTUNG | BSP | Chutipat@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 32 | 11504266 | 22-Jun-2015 | SER0000034 | ค่ากำจัด Grinding from RSH | 250.00 | Metric Tonnes | MRS. CHUTIPA TEANGTUNG | BSP | Chutipat@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 33 | 11504267 | 22-Jun-2015 | SER0000034 | ค่ากำจัด Waste oil | 50.00 | Metric Tonnes | MRS. CHUTIPA TEANGTUNG | BSP | Chutipat@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 34 | 11504269 | 22-Jun-2015 | SER0000034 | ค่ากำจัด Waste grease | 50.00 | Metric Tonnes | MRS. CHUTIPA TEANGTUNG | BSP | Chutipat@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 35 | 11504271 | 22-Jun-2015 | SER0000034 | ค่ากำจัดวัสดุขี้ขี้มัน | 150.00 | Metric Tonnes | MRS. CHUTIPA TEANGTUNG | BSP | Chutipat@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 36 | 11504272 | 22-Jun-2015 | SER0000034 | ค่ากำจัดดินจากการทำความสะอาดเป็นอน้ำมัน | 300.00 | Metric Tonnes | MRS. CHUTIPA TEANGTUNG | BSP | Chutipat@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 37 | 11504273 | 22-Jun-2015 | SER0000034 | ค่ากำจัด Dust from heat recuperator | 100.00 | Metric Tonnes | MRS. CHUTIPA TEANGTUNG | BSP | Chutipat@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 38 | 11504532 | 26-Jun-2015 | SER0000026 | REPAIR AND CALIBRATE MEGAOHM METER 5000V. FLUKE 1550B | 1.00 | JOB | MR. EKKAPONG THONGDEE | BSP | EkkapongT@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 39 | 11504317 | 24-Jun-2015 | SER0000027 | ว่าจ้าง Overhaul air compressor No.1 QSI245 WC S/N 99743 | 1.00 | JOB | MR. EKKAPONG THONGDEE | BSP | EkkapongT@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 40 | 11504646 | 3-Jul-2015 | SER0000027 | REPAIR MOTOR AC 380V 3kw. (เครื่องเดินน้ำมัน) NO.1 | 1.00 | JOB | MR. EKKAPONG THONGDEE | BSP | EkkapongT@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 41 | 11504646 | 3-Jul-2015 | SER0000027 | REPAIR MOTOR AC 380V 3kw. (เครื่องเดินน้ำมัน) NO.2 | 1.00 | JOB | MR. EKKAPONG THONGDEE | BSP | EkkapongT@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 42 | 11504650 | 3-Jul-2015 | SER0000027 | REPAIR AIR COMPRESSOR UNIT MODEL.SSR-ML250 (NO.4) [S/N.11719] | 1.00 | JOB | MR. EKKAPONG THONGDEE | BSP | EkkapongT@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 43 | 11504045 | 22-Jun-2015 | SER0000028 | REPAIR ELECTRONICA SANTERNO INVERTER TYPE "SINUS PENTA 0250" | 1.00 | JOB | MR. EKKAPONG THONGDEE | BSP | EkkapongT@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 44 | 11504168 | 25-Jun-2015 | SER0000028 | REPAIR DYNAC CRANE ACCESSORIER D2C004FV53A001L 4KW 380V | 1.00 | JOB | MR. EKKAPONG THONGDEE | BSP | EkkapongT@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 45 | 11504460 | 26-Jun-2015 | SER0000028 | OVERHAUL MOTOR AC.380V 15KW 1460RPM TYPE 180M4 (B3) A4C1842AA759 (REF.S/N K-13082) "MARELLIMOTOR" S/N No.L-7516 | 1.00 | JOB | MR. EKKAPONG THONGDEE | BSP | EkkapongT@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 46 | 11504529 | 26-Jun-2015 | SER0000028 | ค่าปเกลียว มูเล | 1.00 | JOB | MR. EKKAPONG THONGDEE | BSP | EkkapongT@ssi-steel.com | INCOMPLETE | 13-Jul-15 |

| Serial | PR No. | Document Date | Item Code | PR Line Description | PR Qty | Unit | Buyer | Buyer site | EMAIL ADDRESS | PR Status | RFQ Closing Dated |
|--------|----------|---------------|------------|--|--------|------|--------------------------|------------|--|------------|-------------------|
| 47 | 11504590 | 1-Jul-2015 | SER0000028 | ONLINE TEST SYNCHRONOUS MOTOR 4500 KW FOR MAIN DRIVE F7 | 1.00 | JOB | MR. EKKAPONG THONGDEE | BSP | EkkapongT@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 48 | 11504641 | 1-Jul-2015 | SER0000028 | UNINSTALL AND INSTALL FOR MOTOR ROT =12 EA (SHUTDOWN HSM) | 1.00 | JOB | MR. EKKAPONG THONGDEE | BSP | EkkapongT@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 49 | 11504328 | 25-Jun-2015 | SER0000030 | ซ่อมบอร์ด CPU,PENTIUM 233MHZ COMPL.RAM 32MB PN.053847-1 (S/N : 9918, S/N : 0143) | 2.00 | Each | MR. EKKAPONG THONGDEE | BSP | EkkapongT@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 50 | 11504329 | 25-Jun-2015 | SER0000030 | ซ่อมบอร์ด SCANNER AUXILIARY INTERFACE BOARD P/N.061310 | 1.00 | Each | MR. EKKAPONG THONGDEE | BSP | EkkapongT@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 51 | 11504742 | 3-Jul-2015 | SER0000030 | Siemens service | 1.00 | JOB | MR. EKKAPONG THONGDEE | BSP | EkkapongT@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 52 | 11503995 | 29-Jun-2015 | SER0000027 | REPAIR PROPORTIONAL VALVES D651-308A P70FBM 2CNFA [S/N.D135] | 1.00 | JOB | MR. PATIYUTH DECHPICHAI | BKK | PatiyuthD@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 53 | 11503996 | 29-Jun-2015 | SER0000027 | REPAIR PROPORTIONAL VALVES MODEL D651-307D TYPE U70FQEACN6AOM [S/N.D129] | 1.00 | JOB | MR. PATIYUTH DECHPICHAI | BKK | PatiyuthD@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 54 | 11503997 | 29-Jun-2015 | SER0000027 | REPAIR PROPORTIONAL VALVES MODEL D651-307 G-5 TYPE U70FQEACN6AOM [S/N.D166] | 1.00 | JOB | MR. PATIYUTH DECHPICHAI | BKK | PatiyuthD@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 55 | 11503998 | 29-Jun-2015 | SER0000027 | REPAIR PROPORTIONAL VALVES TYPE D651-308 G-5 U70FQEBCN6AOM [S/N.D167] | 1.00 | JOB | MR. PATIYUTH DECHPICHAI | BKK | PatiyuthD@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 56 | 11504464 | 25-Jun-2015 | SER0000026 | ว่าจ้างซ่อมอุปกรณ์ ชุดเตาร่างเค้น ยี่ห้อ VICTOR พร้อมเปลี่ยนอะไหล่ที่ชำรุด | 1.00 | JOB | MR. PHAIBOON ONCHAWIANG | BSP | PhaiboonO@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 57 | 11504538 | 27-Jun-2015 | SER0000027 | ซ่อม PNEUMATIC SEALER MODEL: PS21 อากาศ : สลักหักและพื้นรับหัก | 1.00 | Each | MR. PHAIBOON ONCHAWIANG | BSP | PhaiboonO@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 58 | 11504651 | 1-Jul-2015 | SER0000027 | ว่าจ้างซ่อมบล็อกลมขนาดแกน 1" [S/N.7120500243] CENTRAL STORE. | 1.00 | JOB | MR. PHAIBOON ONCHAWIANG | BSP | PhaiboonO@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 59 | 11504651 | 1-Jul-2015 | SER0000027 | ว่าจ้างซ่อมบล็อกลมขนาดแกน 3/4" [S/N.7120500241] CENTRAL STORE. | 1.00 | JOB | MR. PHAIBOON ONCHAWIANG | BSP | PhaiboonO@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 60 | 11504651 | 1-Jul-2015 | SER0000027 | ว่าจ้างซ่อมบล็อกลมขนาดแกน 3/4" [S/N.7120500306] CENTRAL STORE. | 1.00 | JOB | MR. PHAIBOON ONCHAWIANG | BSP | PhaiboonO@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 61 | 11504717 | 1-Jul-2015 | SER0000013 | ซ่อมชุดตรวจมวลสัณยศาสตร์ - ทะเยียน ดด-7115 ฝ่าย PUG | 1.00 | JOB | MISS PHONNAPAT SAKHAN | BSP | phonnapatsa@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 62 | 11504637 | 1-Jul-2015 | SER0000020 | ว่าจ้างซ่อมกล่องประตูเครนเบอร์ 55 พร้อมเปลี่ยนอุปกรณ์ ที่ชำรุด จำนวน 1 JOB | 1.00 | JOB | MISS PHONNAPAT SAKHAN | BSP | phonnapatsa@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 63 | 11504162 | 22-Jun-2015 | SER0000026 | ว่าจ้างซ่อมแซมหัวแก๊งรถ Dump truck No.3 | 1.00 | JOB | MISS PHONNAPAT SAKHAN | BSP | phonnapatsa@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 64 | 11504575 | 30-Jun-2015 | SER0000027 | ว่าจ้างติดตั้งเกจวัดแรงดันน้ำมัน เครื่องยนต์ของระบบ cooling Furnace 1,2 | 1.00 | JOB | MISS PHONNAPAT SAKHAN | BSP | phonnapatsa@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 65 | 11504576 | 30-Jun-2015 | SER0000027 | ว่าจ้างตรวจเช็คและซ่อมถังน้ำมันเชื้อเพลิงรถเทลเลอร์ เบอร์ 3 (จำนวน 2 ใบ) | 1.00 | JOB | MISS PHONNAPAT SAKHAN | BSP | phonnapatsa@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 66 | 11504383 | 26-Jun-2015 | SER0000013 | ซ่อมวิทยุสื่อสาร 6 เครื่อง | 1.00 | JOB | MISS PITTAYARAT PHUENPHA | BSP | pittayaratph@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 67 | 11504573 | 26-Jun-2015 | SER0000013 | ซ่อมวิทยุสื่อสาร 4 เครื่อง | 1.00 | JOB | MISS PITTAYARAT PHUENPHA | BSP | pittayaratph@ssi-steel.com | INCOMPLETE | 13-Jul-15 |
| 68 | 11504837 | 3-Jul-2015 | SER0000024 | ค่าเช่า UIH Internet 20/15Mbps (Fiber) | 12.00 | JOB | MR. SIRICHAJ PROMCHAN | BKK | SirichaiPr@ssi-steel.com | INCOMPLETE | 13-Jul-15 |