

PR Received dated 22 Aug 2016 - 28 Aug 2016

Services & Others

Post Dated 29 Aug 2016

Serial	PR No.	Document Date	Item Code	PR Line Description	PR Qty	Unit	Buyer	Buyer site	EMAIL ADDRESS	PR Status	RFQ Closing Dated
1	11606480	24-Aug-2016	SER0000026	ว่าจ้างซ่อม HAND PUMP P-392 "ENERPAC" [S/N.7151200002]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
2	11606480	24-Aug-2016	SER0000026	ว่าจ้างซ่อม HAND PUMP P-392 "ENERPAC" [S/N.1HY090107]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
3	11606480	24-Aug-2016	SER0000026	ว่าจ้างซ่อม HAND PUMP P-392 "ENERPAC" [S/N.7130400013]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
4	11606480	24-Aug-2016	SER0000026	ว่าจ้างซ่อม HAND PUMP P-392 "ENERPAC" [S/N.7130400014]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
5	11606480	24-Aug-2016	SER0000026	ว่าจ้างซ่อม HAND PUMP P-392 "ENERPAC" [S/N.7151200128]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
6	11603674	22-Aug-2016	SER0000027	ว่าจ้างซ่อม housing of Omega pump series 350-510A	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
7	11605074	25-Aug-2016	SER0000027	REPAIR TILT CYLINDER P/N.2144.51051 (BORE = 180/ ROD = 80 / St = 310 MM.) FOR FANTUZZI	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
8	11605075	26-Aug-2016	SER0000027	REPAIR UPPER EXIT GUIDE COMP.SETG05464(F1-F6) [NEED CHECK SHEET INSP.] (NO.1)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
9	11605075	26-Aug-2016	SER0000027	REPAIR UPPER EXIT GUIDE COMP.SETG05464(F1-F6) [NEED CHECK SHEET INSP.] (NO.2)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
10	11605464	26-Aug-2016	SER0000027	REPAIR SELF CLEANING FILTER MOD.AKO RB-10 FOR WTP.	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
11	11605908	23-Aug-2016	SER0000027	REPAIR REDUCTION GEAR BOX RIV125U02AA I=254(NO.2/3) FOR WTP.	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
12	11606245	23-Aug-2016	SER0000027	REPAIR HYD.CYL.1000-10285 (NO.12) FOR WR.CLAMP FIM.	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
13	11606246	23-Aug-2016	SER0000027	REPAIR HYD.CYL.1000-10285 (NO.3) FOR WR.CLAMP FIM.	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
14	11606251	23-Aug-2016	SER0000027	REPAIR HYD.CYL.PARKER 3.25BB2H-RS-14M6.25" (STAND S,Q,#6) FOR STAND SQ,#6 PPPL	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
15	11606373	25-Aug-2016	SER0000027	REPAIR AIR CYLINDER "HANNIFIN" P-160006 (NO.1) FOR DOC.	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
16	11606373	25-Aug-2016	SER0000027	REPAIR AIR CYLINDER "HANNIFIN" P-160006 (NO.2) FOR DOC.	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
17	11606375	25-Aug-2016	SER0000027	REPAIR PREFILLING VALVE TYPE 2-VDS-08-V6 NP315 [S/N.3/11] (NEED CHECK SHEET INSP.)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
18	11606478	25-Aug-2016	SER0000027	REPAIR SPINDLE WITH ROLL SLEEVE G05627 POS.1,3-20 FOR F4-F6 (KOPFLEX) [NO.11] (NEED CHECK SHEET INSP)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
19	11606478	25-Aug-2016	SER0000027	REPAIR SPINDLE WITH ROLL SLEEVE G05627 POS.1,3-20 FOR F4-F6 (KOPFLEX) [NO.9] (NEED CHECK SHEET INSP)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
20	11606659	25-Aug-2016	SER0000027	REPAIR ROLLER SIDE GUIDE FM COMP.SET (1 ST) L= 400 mm (DWG.003483 REV.B) [NO.1]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
21	11606659	25-Aug-2016	SER0000027	REPAIR ROLLER SIDE GUIDE FM COMP.SET (1 ST) L= 400 mm (DWG.003483 REV.B) [NO.2]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
22	11606659	25-Aug-2016	SER0000027	REPAIR ROLLER SIDE GUIDE FM COMP.SET (1 ST) L= 400 mm (DWG.003483 REV.B) [NO.3]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
23	11606659	25-Aug-2016	SER0000027	REPAIR ROLLER SIDE GUIDE FM COMP.SET (1 ST) L= 400 mm (DWG.003483 REV.B) [NO.4]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
24	11606660	25-Aug-2016	SER0000027	REPAIR CENTRIPUGAL PUMP "KSB" IMP.466mm. (ETA 250-09) FOR WTP.	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
25	11606661	23-Aug-2016	SER0000027	REPAIR HYD.CYL.1000-10405 DWG.M74650 FOR TOP ENTRY PINCH ROLL SKM#2	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
26	11606671	23-Aug-2016	SER0000027	REPAIR HYD. CYL. ""FOSSA"" TYPE 1000-19118 DWS.106230/A FOR LOAD CAR AND UNLOAD CAR UP-DOWN SKM#3	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
27	11606691	25-Aug-2016	SER0000027	REPAIR HYD. CYL.1000-19104 " FOSSA " (G54589) [NO.3]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
28	11606692	25-Aug-2016	SER0000027	REPAIR HYD.CYL.1000-15952 SMS-DEMAG G-53806 SG DC [NO.11]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
29	11607201	22-Aug-2016	SER0000027	ว่าจ้าง Fabricate and install water seal slope zone 6 for furnace	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
30	11607260	22-Aug-2016	SER0000027	REPAIR BOTTOM STRIPPER WR R1 No.7 และ No.11-รายละเอียดตามเอกสารแนบ	2.00	Each	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
31	11607294	22-Aug-2016	SER0000027	REPAIR HYD.CYL.1000-10283 FOR SHIFTING F4-F7 (NO.18) FOR SHIFTING FIM.	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
32	11607295	22-Aug-2016	SER0000027	REPAIR HYD.CYL.1000-10283 FOR SHIFTING F4-F7 (NO.19) FOR SHIFTING FIM.	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016

PR Received dated 22 Aug 2016 - 28 Aug 2016

Services & Others

Post Dated 29 Aug 2016

Serial	PR No.	Document Date	Item Code	PR Line Description	PR Qty	Unit	Buyer	Buyer site	EMAIL ADDRESS	PR Status	RFQ Closing Dated
33	11607351	26-Aug-2016	SER0000027	REPAIR BOTTOM PINCH ROLL DIA.510 mm (NO.3) [NEED CHECK SHEET ISNP.]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
34	11607351	26-Aug-2016	SER0000027	REPAIR BOTTOM PINCH ROLL DIA.510 mm (NO.7) [NEED CHECK SHEET ISNP.]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
35	11607352	26-Aug-2016	SER0000027	REPAIR GEAR BOX BIDGE ADK80DD ADK80DD (DEMAG) WITH TORQUE ARM FOR OHC	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
36	11607357	26-Aug-2016	SER0000027	Re-lining Roll Tension Bridle Dia. 915x1981 mm. (Mat.Esther PU, Roll Profile : Flat, Surface Roughness : Flat, Hardness 85 - 90 Shore A)	1.00	Roll	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
37	11607358	26-Aug-2016	SER0000027	Re-lining Pinch Roll # 1 Dia.305x1980 mm. (Mat.Ether PU, Roll Profile : Taper, Surface Roughness : Flat, Hardness 80-85 Duro A)	1.00	Roll	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
38	11607359	26-Aug-2016	SER0000027	Re-lining Squeegee Roll Dia.255x2440 mm. (Mat.Neoprene, Roll Profile : Crown, Hardness 50 - 65 Shore A)	5.00	Roll	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
39	11607360	26-Aug-2016	SER0000027	Grinding Squeegee Roll Dia.255x2440 mm.(Mat.Neoprene, Roll Profile : Crown, Hardness 50 - 70 Shore A)	3.00	Roll	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
40	11607397	26-Aug-2016	SER0000027	REPAIR ANTI COIL BREAK ROLLER COMPLETE SET DWG.M74777 (NO.1) FOR SKM#1	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
41	11607397	26-Aug-2016	SER0000027	REPAIR ANTI COIL BREAK ROLLER COMPLETE SET DWG.M74777 (NO.2) FOR SKM#1	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
42	11607398	26-Aug-2016	SER0000027	REPAIR MILL SPINDLE TYPE M 1032 COMPLETE SET(POS.1 TO 24) DWG.2M00790 REV.B FOR STAND MILL SKM1	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
43	11607402	26-Aug-2016	SER0000027	REPAIR PREFILLING VALVE TYPE 2-VDS-08-V6 NP315 (NO.5/11)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
44	11607403	26-Aug-2016	SER0000027	REPAIR DESCALING VALVE 4" 2-WAY MOD.4108A P/N 97933941 (NO.1/9)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	5-Sep-2016
45	11607186	26-Aug-2016	SER0000026	ซ่อมบำรุงรักษาเครื่องทดสอบออกซิเจน ในโตเจน	1.00	JOB	MONTHATONG, MISS AREERAT	BSP	AreeratM@ssi-steel.local	INCOMPLETE	5-Sep-2016
46	11607181	23-Aug-2016	SER0000028	OVERHAUL MOTOR AC. 40-380V 3.7KW 100-1075RPM B4R160M6 (B3) FOR RUNOUT TABLE (5EA)	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	5-Sep-2016
47	11607182	23-Aug-2016	SER0000028	OVERHAUL MOTOR AC 55KW 380/660V 102.6/59.2A 50HZ B3 2P	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	5-Sep-2016
48	11607364	26-Aug-2016	SER0000028	REWINDING MOTOR AC.380V.250KW.1490RPM.TYPE M2CA355MA-4(B3) S/N.3266053	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	5-Sep-2016
49	11607365	26-Aug-2016	SER0000028	REWINDING MOTOR AC 7.5KW 15.4/8.9A 1460RPM TYPE 160M/4 (B3) A4C1642AA759 S/N.K13103	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	5-Sep-2016
50	11607366	26-Aug-2016	SER0000028	OVERHAUL OVERHUAL MOTOR AC. 380V 11KW 1460 RPM TYPE 160M/4 IMB3	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	5-Sep-2016
51	11607375	26-Aug-2016	SER0000028	ทดสอบค่าทางไฟฟ้าของอุปกรณ์สถานีไฟฟ้า 115 kV	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	5-Sep-2016
52	11607377	26-Aug-2016	SER0000028	ทดสอบน้ำมันหม้อแปลงตาม PM Sep 16 ทั้งหมด 24 ลูก	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	5-Sep-2016
53	11607396	26-Aug-2016	SER0000028	ADD. PO.41604198 MAKE BASEMENT OF MOTOR AC. 220/380V 7.5KW 1450RPM TYPE MA132MA4(B35)	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	5-Sep-2016
54	11607288	22-Aug-2016	SER0000016	ว่าจ้างซ่อมหลังคาเป็นรูรั่ว	1.00	JOB	JANTHAWEE, MISS JARIYAPORN	BSP	jariyapornja@ssi-steel.com	INCOMPLETE	5-Sep-2016
55	11607281	26-Aug-2016	SER0000027	REPAIR STARTER MOTOR 24V P/N 4881097-2 FOR ENGINE VOLVO TD71A FANTUZZI(F-6)	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	5-Sep-2016
56	11607283	26-Aug-2016	SER0000027	REPAIR STARTER MOTOR 24V P/N 4881097-2 FOR ENGINE VOLVO TD71A FANTUZZI (F-4)	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	5-Sep-2016
57	11607285	26-Aug-2016	SER0000027	REPAIR STARTER MOTOR 24V P/N 4881097-2 FOR ENGINE VOLVO TD71A FANTUZZI (F-3)	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	5-Sep-2016
58	11607286	26-Aug-2016	SER0000027	REPAIR STARTER MOTOR 24V P/N 4881097-2 FOR ENGINE VOLVO TD71A FANTUZZI (F-13)	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	5-Sep-2016
59	11607287	26-Aug-2016	SER0000027	REPAIR STARTER MOTOR GP-ELECTRIC 24 VOLT P/N. 207-1556 (OLD P/N.106-8553 AND P/N.8T9685) FOR KRESS (K-303)	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	5-Sep-2016
60	11607289	26-Aug-2016	SER0000027	REPAIR STARTER MOTOR GP-ELECTRIC 24 VOLT P/N. 207-1556 (OLD P/N.106-8553 AND P/N.8T9685) FOR KRESS (K-302)	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	5-Sep-2016
61	11607291	26-Aug-2016	SER0000027	REPAIR STARTER MOTOR GP-ELECTRIC 24 VOLT P/N. 207-1556 (OLD P/N.106-8553 AND P/N.8T9685) FOR KRESS (K-301)	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	5-Sep-2016
62	11607292	26-Aug-2016	SER0000027	REPAIR ALTERNATOR GR-CHARGING P/N.100-5047 FOR KRESS (K-301)	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	5-Sep-2016
63	11606573	26-Aug-2016	SER0000027	Commissioning and installation load cell under back up roll installation type	1.00	JOB	PHETPHO, MR. TANAPOL	BKK	tanapolp@ssi-steel.com	INCOMPLETE	5-Sep-2016