

Serial	PR No.	Document Date	Item Code	PR Line Description	PR Qty	Unit	Buyer	Buyer site	EMAIL ADDRESS	PR Status	RFQ Cloing Dated
1	11501175	18-Feb-2015	SER0000027	REPAIR HYD.CYL PARKER 4D2HLR 23M 45.69(ANTY-COIL BREAK) PO-LINE.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	2-Mar-15
2	11501176	18-Feb-2015	SER0000027	REPAIR DIAPHRAGM VALVE 8" PART NO.DVK080PF FOR PO-LINE.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	2-Mar-15
3	11501177	18-Feb-2015	SER0000027	REPAIR BRAKE CYLINDER P/N 2144.964001 (NO.1) FOR VEH.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	2-Mar-15
4	11501177	18-Feb-2015	SER0000027	REPAIR BRAKE CYLINDER P/N 2144.964001 (NO.2) FOR VEH.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	2-Mar-15
5	11501177	18-Feb-2015	SER0000027	REPAIR BRAKE CYLINDER P/N 2144.964001 (NO.3) FOR VEH.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	2-Mar-15
6	11501178	18-Feb-2015	SER0000027	REPAIR BRAKE CYLINDER P/N 2144.964001 (NO.01)	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	2-Mar-15
7	11501178	18-Feb-2015	SER0000027	REPAIR BRAKE CYLINDER P/N 2144.964001 (NO.02)	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	2-Mar-15
8	11501178	18-Feb-2015	SER0000027	REPAIR BRAKE CYLINDER P/N 2144.964001 (NO.03)	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	2-Mar-15
9	11501179	18-Feb-2015	SER0000027	REPAIR STEERING CYLINDER P/N 243070(NO.1) FOR FANTUZZI.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	2-Mar-15
10	11501179	18-Feb-2015	SER0000027	REPAIR STEERING CYLINDER P/N 243070(NO.2) FOR FANTUZZI.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	2-Mar-15
11	11501181	18-Feb-2015	SER0000027	REPAIR ASS'Y ARM STEERING & BEARING COMPLETE SET P/N.2325.832501 (MMDDD004233)[NO.1]	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	2-Mar-15
12	11501181	18-Feb-2015	SER0000027	REPAIR ASS'Y ARM STEERING & BEARING COMPLETE SET P/N.2325.832501 (MMDDD004233)[NO.2]	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	2-Mar-15
13	11501182	18-Feb-2015	SER0000027	REPAIR HOUSING DIFF. FRAME P/N.AC6.268127 (MMDDD004938) LENGTH = 2070 MM.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	2-Mar-15
14	11501358	21-Feb-2015	SER0000027	WELDING WR EDGER No. 10432,10436	2.00	Roll	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	2-Mar-15
15	11501359	21-Feb-2015	SER0000027	REPAIR TOP BUR CHOCKS F4-F7 NO.9 -ซ่อมรูใน	1.00	Each	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	2-Mar-15
16	11501124	17-Feb-2015	SER0000013	จัดหาเครื่องจักรซ่อม Yard วันละ 8 ชม. 5 วัน ประจำเดือน กพ. 2558	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	2-Mar-15
17	11501217	18-Feb-2015	SER0000026	ซ่อมเทียนเครื่องวัดแก๊ส Multi gas S/N : 128398	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	2-Mar-15
18	11501223	19-Feb-2015	SER0000034	ค่ากำจัด wastewater sludge (ภาคตะกอนจากระบบบำบัดน้ำเสีย)	150.00	Metric Tonnes	MRS. CHUTIPA TEANGTUNG	BSP	Chutipat@ssi-steel.com	INCOMPLETE	2-Mar-15
19	11501172	19-Feb-2015	SER0000013	ซ่อม PNEUMATIC SEALER MODEL: PS21 จำนวน 2 EA อากาศ : สลักหัก	1.00	JOB	MR. PHAIBOON ONCHAWIANG	BSP	PhaiboonO@ssi-steel.com	INCOMPLETE	2-Mar-15
20	11501192	19-Feb-2015	SER0000028	CALIBRATE CLAMP METER FLUKE 337 (FOR SHIFT EMD)	1.00	JOB	MR. PHAIBOON ONCHAWIANG	BSP	PhaiboonO@ssi-steel.com	INCOMPLETE	2-Mar-15
21	11501360	21-Feb-2015	SER9999999	Other service BSP Project :Install RBL at F2&F4 (contact K'Somsak 5264) Items in attachment	1.00	Each	MR. PHAIBOON ONCHAWIANG	BSP	PhaiboonO@ssi-steel.com	INCOMPLETE	2-Mar-15
22	11501180	18-Feb-2015	SER0000027	REPAIR STARTER MOTOR 24V P/N 4881097-2 FOR FANTUZZI.	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	2-Mar-15
23	11500802	19-Feb-2015	SER0000024	ซ่อมแซม อุปกรณ์คอมพิวเตอร์ และ ซอฟต์แวร์	7.00	Each	MR. SIRICHAJ PROMCHAN	BKK	SirichaiPr@ssi-steel.com	INCOMPLETE	2-Mar-15
24	11501169	18-Feb-2015	SER9999999	จัดทำบัญชีทะเบียนรถจักรยาน	1.00	JOB	MRS. SULEEWAN THONGYEET	BSP	SuleewanT@ssi-steel.com	INCOMPLETE	2-Mar-15