

PR Received dated 7 Mar 2016 - 27 Mar 2016

Services & Others

Post Dated 28 Mar 2016

Serial	PR No.	Document Date	Item Code	PR Line Description	PR Qty	Unit	Buyer	Buyer site	EMAIL ADDRESS	PR Status	RFQ Closing Dated
1	11600761	17-Mar-2016	SER0000027	REPAIR VALVE QUICK LIFT 8AP1-8D1-6Y1(69020) FOR KRESS(No.1)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
2	11601549	17-Mar-2016	SER0000027	REPAIR HYD.CYL.1000-10389 G08017.01 (NO.3) FOR COIL CAR TRAVELLING DOC.	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
3	11601692	7-Mar-2016	SER0000027	REPAIR DESCALING PUMP COMPLETE SET DWG.W26858 POS.1-85 [ECO-6398]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
4	11601694	15-Mar-2016	SER0000027	REPAIR HEAT EXCHANGER PBG13SL-3PU-1-1 FOR PO-LINE	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
5	11601696	7-Mar-2016	SER0000027	REPAIR ARM STEERING P/N AE4.243044 (MMDDD004307) (MMDDD003040) [NO.26] FOR REAR AXLE OF FANTUZZI	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
6	11601696	7-Mar-2016	SER0000027	REPAIR ARM STEERING P/N AE4.243044 (MMDDD004307) (MMDDD003040) [NO.40] FOR REAR AXLE OF FANTUZZI	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
7	11601696	7-Mar-2016	SER0000027	REPAIR ARM STEERING P/N AE4.243044 (MMDDD004307) (MMDDD003040) [NO.38] FOR REAR AXLE OF FANTUZZI	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
8	11601696	7-Mar-2016	SER0000027	REPAIR ARM STEERING P/N AE4.243044 (MMDDD004307) (MMDDD003040) [NO.36] FOR REAR AXLE OF FANTUZZI	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
9	11601699	7-Mar-2016	SER0000027	REPAIR ARM STEERING P/N AE4.243044 (MMDDD004307) (MMDDD003040) [NO.3] FOR REAR AXLE OF FANTUZZI	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
10	11601699	7-Mar-2016	SER0000027	REPAIR ARM STEERING P/N AE4.243044 (MMDDD004307) (MMDDD003040) [NO.4] FOR REAR AXLE OF FANTUZZI	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
11	11601699	7-Mar-2016	SER0000027	REPAIR ARM STEERING P/N AE4.243044 (MMDDD004307) (MMDDD003040) [NO.16] FOR REAR AXLE OF FANTUZZI	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
12	11601699	7-Mar-2016	SER0000027	REPAIR ARM STEERING P/N AE4.243044 (MMDDD004307) (MMDDD003040) [NO.13] FOR REAR AXLE OF FANTUZZI	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
13	11601700	7-Mar-2016	SER0000027	REPAIR TONG CYLINDER P/N 125350 [NO.1] FOR KRESS	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
14	11601701	7-Mar-2016	SER0000027	REPAIR TONG CYLINDER P/N 125350 [NO.4] FOR KRESS	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
15	11602036	17-Mar-2016	SER0000027	REPAIR BOTTOM BENDING ROLL ASS"YDWG.K-360139 [FOLLOW REP.MANUAL],[NEED CHECK SHEEET INSP]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
16	11602076	15-Mar-2016	SER0000027	ว่าจ้างประกอบ HYD. MANDREL DC#1	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
17	11602183	17-Mar-2016	SER0000027	REPAIR HYD.CYL. 1000-10276 FOR LOWER EXIT GUIDE LIFTING FM (NO.1)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
18	11602184	17-Mar-2016	SER0000027	REPAIR BALANCING BLOCK EXIT O/S G05577 POS.3-26(F4-F7) (NO.1)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
19	11602185	17-Mar-2016	SER0000027	REPAIR HYD.CYL 1000-10374 G06945.01(NO.4) [NEED CHECK SHEET INSP.]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
20	11602187	16-Mar-2016	SER0000027	REPAIR HYD. BENDING STAND SKM#1,2 M74599 ASS-Y COMPLETE SET.	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
21	11602296	22-Mar-2016	SER0000027	REPAIR TOP LEVELING ROLL COMP.SET MODIFY DIA.80 MM. SKM#2 MMDDD003340 REV.B (NO.1)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
22	11602296	22-Mar-2016	SER0000027	REPAIR TOP LEVELING ROLL COMP.SET MODIFY DIA.80 MM. SKM#2 MMDDD003340 REV.B (NO.2)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
23	11602296	22-Mar-2016	SER0000027	REPAIR TOP LEVELING ROLL COMP.SET MODIFY DIA.80 MM. SKM#2 MMDDD003340 REV.B (NO.4)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
24	11602296	22-Mar-2016	SER0000027	REPAIR TOP LEVELING ROLL COMP.SET MODIFY DIA.80 MM. SKM#2 MMDDD003340 REV.B (NO.3)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
25	11602297	22-Mar-2016	SER0000027	REPAIR BTM.LEVELLING ROLL MODIFY SHAFT DIA.80MM. COMP.SET SKM#2 (MMDDD002644) FOR SKM#2 (NO.1)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
26	11602297	22-Mar-2016	SER0000027	REPAIR BTM.LEVELLING ROLL MODIFY SHAFT DIA.80MM. COMP.SET SKM#2 (MMDDD002644) FOR SKM#2 (NO.2)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
27	11602305	23-Mar-2016	SER0000027	REPAIR IDLE ROLL UNLOAD CAR SKM#1 M74521 REV.D COMPLETE SET	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	4-Apr-2016
28	11602037	17-Mar-2016	SER0000027	ว่าจ้างเปลี่ยน seal HYDRAULIC CYLINDER B100-70/300ST (WEIGHT SCALE)	1.00	JOB	PIKKANESUAN, MRS. ANCHALEE	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	4-Apr-2016

PR Received dated 7 Mar 2016 - 27 Mar 2016

Services & Others

Post Dated 28 Mar 2016

Serial	PR No.	Document Date	Item Code	PR Line Description	PR Qty	Unit	Buyer	Buyer site	EMAIL ADDRESS	PR Status	RFQ Closing Dated
29	11601752	7-Mar-2016	SER0000026	สอบเทียบเครื่องวัดความเร็วลม	1.00	JOB	CHUMBOON, MRS. MONTHA	BSP	MonthaA@ssi-steel.com	INCOMPLETE	4-Apr-2016
30	11600477	11-Mar-2016	SER0000020	ว่าจ้างเปลี่ยนกระจกบานหน้าของเครน*55ที่ชำรุด	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	4-Apr-2016
31	11601673	11-Mar-2016	SER0000026	ว่าจ้างเชื่อมซ่อมและ M/C คานหลังรถ Toyota F/L 5FDJ35 No.1	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	4-Apr-2016
32	11601972	11-Mar-2016	SER0000026	ว่าจ้างตรวจเช็คและซ่อมสลักคลมขนาด 1/2 นิ้ว "Ingersoll Rand" จำนวน 1 ตัว	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	4-Apr-2016
33	11600762	11-Mar-2016	SER0000027	REPAIR STARTER MOTOR GP-ELECTRIC 24 VOLT P/N. 207-1556 (OLD P/N.106-8553 AND P/N.8T9685) [S/N.1986451] FOR KRESS	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	4-Apr-2016
34	11600762	11-Mar-2016	SER0000027	REPAIR STARTER MOTOR GP-ELECTRIC 24 VOLT P/N. 207-1556 (OLD P/N.106-8553 AND P/N.8T9685) [S/N.322451] FOR KRESS	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	4-Apr-2016
35	11601546	15-Mar-2016	SER0000027	ว่าจ้างทำป้ายติดบอร์ดประชาสัมพันธ์ TPM	1.00	JOB	PHUENPHA, MISS PITTAYARAT	BSP	pittayaratph@ssi-steel.com	INCOMPLETE	4-Apr-2016
36	11602086	17-Mar-2016	SER0000027	ว่าจ้างทำป้าย Tag TPM แบบพลาสติก	1.00	JOB	PHUENPHA, MISS PITTAYARAT	BSP	pittayaratph@ssi-steel.com	INCOMPLETE	4-Apr-2016
37	11601761	18-Mar-2016	SER0000024	MA Software Veeam (Renewal coverage period : 13 November 2015 - 12 November 2016)	8.00	Each	PROMCHAN, MR. SIRICHAJ	BKK	SirichaiPr@ssi-steel.com	INCOMPLETE	4-Apr-2016
38	11602369	25-Mar-2016	SER0000024	ซ่อม Printer HP Laser Jet 2430n A/C : 5000303200	1.00	Each	PROMCHAN, MR. SIRICHAJ	BKK	SirichaiPr@ssi-steel.com	INCOMPLETE	4-Apr-2016