

PR Received dated 9 May 2016 - 15 May 2016

Services & Others

Post Dated 16 May 2016

Serial	PR No.	Document Date	Item Code	PR Line Description	PR Qty	Unit	Buyer	Buyer site	EMAIL ADDRESS	PR Status	RFQ Closing Dated
1	11601693	11-May-2016	SER0000027	REPAIR UPPER ROLL OF TENSION LEVELLER DWG.510351 POS.12,13,16,17,67,68,103,105 COMP. SET FOR TENSION LEVELLER (NO.1)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	23-May-2016
2	11601693	11-May-2016	SER0000027	REPAIR UPPER ROLL OF TENSION LEVELLER DWG.510351 POS.12,13,16,17,67,68,103,105 COMP. SET FOR TENSION LEVELLER (NO.2)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	23-May-2016
3	11602036	9-May-2016	SER0000027	REPAIR BOTTOM BENDING ROLL ASS"YDWG.K-360139 [FOLLOW REP.MANUAL],[NEED CHECK SHEET INSP]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	23-May-2016
4	11602296	9-May-2016	SER0000027	REPAIR TOP LEVELING ROLL COMP.SET MODIFY DIA.80 MM. SKM#2 MMDDD003340 REV.B (NO.1)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	23-May-2016
5	11602296	9-May-2016	SER0000027	REPAIR TOP LEVELING ROLL COMP.SET MODIFY DIA.80 MM. SKM#2 MMDDD003340 REV.B (NO.2)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	23-May-2016
6	11602296	9-May-2016	SER0000027	REPAIR TOP LEVELING ROLL COMP.SET MODIFY DIA.80 MM. SKM#2 MMDDD003340 REV.B (NO.3)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	23-May-2016
7	11602296	9-May-2016	SER0000027	REPAIR TOP LEVELING ROLL COMP.SET MODIFY DIA.80 MM. SKM#2 MMDDD003340 REV.B (NO.4)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	23-May-2016
8	11602297	9-May-2016	SER0000027	REPAIR BTM.LEVELLING ROLL MODIFY SHAFT DIA.80MM. COMP.SET SKM#2 (MMDDD002644) FOR SKM#2 (NO.1)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	23-May-2016
9	11602297	9-May-2016	SER0000027	REPAIR BTM.LEVELLING ROLL MODIFY SHAFT DIA.80MM. COMP.SET SKM#2 (MMDDD002644) FOR SKM#2 (NO.2)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	23-May-2016
10	11602727	9-May-2016	SER0000027	REPAIR FEEDER ROLL NO.1-2 ASS-Y COMPLETE SET DWG.G05203 POS.1,3-12 [NO.1-2] (NEED CHECK SHEET INSP.)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	23-May-2016
11	11602783	9-May-2016	SER0000027	ว่าจ้างประกอบ Guide rod crop shear SKM#1	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	23-May-2016
12	11603036	10-May-2016	SER0000027	REPAIR HYD.CYL."REXROTH"CDT3 63 F11 HUM FOR W/R CLAMP SKM#1,2	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	23-May-2016
13	11603375	13-May-2016	SER0000027	ว่าจ้างเปลี่ยน Bearing และซ่อม Frame Pinch roll COB	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	23-May-2016
14	11603405	9-May-2016	SER0000027	ซ่อมแซมผิว BRIDLE ROLL Dia.1220 mm. Shaft 6 15/16" โดยการเจียรผิวและพ่นพอก Tungstan carbide จำนวน 1 Rolls ใต้แก๊ส Roll No.09	1.00	Roll	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	23-May-2016
15	11603689	9-May-2016	SER0000027	ว่าจ้างตรวจสอบศูนย์และจารู flange ล้อครน No.35	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	23-May-2016
16	11603838	10-May-2016	SER0000027	Re-lining Squeegee Roll Dia.255x2440 mm. (Mat.Neoprene, Roll Profile : Crown,Hardness 50 - 65 Shore A)	8.00	Roll	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	23-May-2016
17	11603839	10-May-2016	SER0000027	Grinding Squeegee Roll Dia.255x2440 mm.(Mat.Neoprene, Roll Profile : Crown,Hardness 50 - 70 Shore A)	3.00	Roll	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	23-May-2016
18	11603854	10-May-2016	SER0000023	ปรับปรุงแผงวงจรสายโทรศัพท์ภายใน 8 เบอร์	1.00	Each	SEEBAMRUNGSAS, MISS PAON	BKK	PaonS@ssi-steel.com	INCOMPLETE	23-May-2016
19	11603854	10-May-2016	SER0000023	ปรับปรุงแผงวงจรสายโทรศัพท์สายนอก 8 เบอร์	1.00	Each	SEEBAMRUNGSAS, MISS PAON	BKK	PaonS@ssi-steel.com	INCOMPLETE	23-May-2016
20	11603771	9-May-2016	SER0000027	ว่าจ้างตรวจเช็คและซ่อมเทอร์โบรถ Mobile crane TADANO NO.1	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	23-May-2016
21	11603805	12-May-2016	SER0000027	ว่าจ้างตรวจเช็คและแก้ไขไดสตาร์ทรถบรรทุกติดเครน เบอร์ 1	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	23-May-2016
22	11603876	12-May-2016	SER0000027	ว่าจ้างซ่อมและ M/C BEARING BUSH รหัส FANTUZZI	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	23-May-2016
23	11603845	9-May-2016	SER0000024	UTP CABLE CAT5E LINK US-9015 (305/BOX)	1.00	Each	PROMCHAN, MR. SIRICHAJ	BKK	SirichaiPr@ssi-steel.com	INCOMPLETE	23-May-2016
24	11603846	9-May-2016	SER0000024	Mouse Optical USB Logitech M100R	20.00	Each	PROMCHAN, MR. SIRICHAJ	BKK	SirichaiPr@ssi-steel.com	INCOMPLETE	23-May-2016
25	11603856	11-May-2016	SER0000024	MAอุปกรณ์ PocketPC	1.00	JOB	PROMCHAN, MR. SIRICHAJ	BKK	SirichaiPr@ssi-steel.com	INCOMPLETE	23-May-2016
26	11603863	11-May-2016	SER0000024	Battery Notebook DELL LATITUDE 6430u (5000104098)	1.00	Each	PROMCHAN, MR. SIRICHAJ	BKK	SirichaiPr@ssi-steel.com	INCOMPLETE	23-May-2016
27	11603864	11-May-2016	SER0000024	Battery Notebook DELL LATITUDE 6430u (5000104101)	1.00	Each	PROMCHAN, MR. SIRICHAJ	BKK	SirichaiPr@ssi-steel.com	INCOMPLETE	23-May-2016
28	11603955	13-May-2016	SER0000024	MA Core Switch WS-C3850-24T-E Catalyst 3850 24 10/100/1000T Data IP Service S/N : FOC1834X04F	1.00	JOB	PROMCHAN, MR. SIRICHAJ	BKK	SirichaiPr@ssi-steel.com	INCOMPLETE	23-May-2016
29	11603965	12-May-2016	SER0000024	Cisco Core Switch : Catalyat 3850 24 10/100/100T Data IP Service Serial Number : FOC1830X0UU	1.00	JOB	PROMCHAN, MR. SIRICHAJ	BKK	SirichaiPr@ssi-steel.com	INCOMPLETE	23-May-2016