

PR Received dated 13 Jun 2016 - 19 Jun 2016

Services & Others

Post Dated 20 Jun 2016

Serial	PR No.	Document Date	Item Code	PR Line Description	PR Qty	Unit	Buyer	Buyer site	EMAIL ADDRESS	PR Status	RFQ Closing Dated
1	11602439	17-Jun-2016	SER0000027	REPAIR HYD.SCREW DOWN F1-F6 ASS G05571,G05521 FULLY ASS'Y (NO.10)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	27-Jun-2016
2	11602440	17-Jun-2016	SER0000027	REPAIR HYD.SCREW DOWN F1-F6 ASS G05571,G05521 FULLY ASS'Y (NO.3)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	27-Jun-2016
3	11603264	16-Jun-2016	SER0000027	REPAIR N.C. TWO WAY VALVE 2"AS YMOD.4105A (NO.3/3) [NEED CHECK SHEET INSP.]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	27-Jun-2016
4	11603530	15-Jun-2016	SER0000027	REPAIR SPINDLE P/N.AC7.268014 (MMDDD004212 REV.A) (NO.1) FOR AXLE FRONT WHEEL HUB OF FANTUZZI	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	27-Jun-2016
5	11603531	15-Jun-2016	SER0000027	REPAIR SPINDLE P/N.AC7.268014 (MMDDD004212 REV.A)(NO.2) FOR AXLE FRONT WHEEL HUB OF FANTUZZI	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	27-Jun-2016
6	11603936	13-Jun-2016	SER0000027	REPAIR TOP PINCH ROLL COMPLETE DOC.(NO.6)	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	27-Jun-2016
7	11604073	17-Jun-2016	SER0000027	REPAIR BOTTOM BUR. CHOCK RM NO.3,4	2.00	Each	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	27-Jun-2016
8	11604379	17-Jun-2016	SER0000027	REPAIR BOTTOM BUR CHOCKS -เชื่อมพอกปรับสภาพผิวฐานล่าง	4.00	Each	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	27-Jun-2016
9	11604945	14-Jun-2016	SER0000027	ว่าจ้างทำ rubber bush coupling CP001,2,5 จำนวน 12 EA	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	27-Jun-2016
10	11604946	16-Jun-2016	SER0000027	Re-lining Squeegee Roll Dia.255x2440 mm. (Mat.Neoprene, Roll Profile : Crown,Hardness 50 - 65 Shore A) จำนวน 3 Rolls ไตหนัก Roll No.13,33,36	3.00	Roll	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	27-Jun-2016
11	11604951	14-Jun-2016	SER0000027	ว่าจ้างติดตั้งและแก้ไขชิ้นงาน Beam Lifting work roll SK 3	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	27-Jun-2016
12	11604960	14-Jun-2016	SER0000027	ว่าจ้างถอด Spindle No. 12 inspection shaft	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	27-Jun-2016
13	11604996	15-Jun-2016	SER0000027	WELDING WR EDGER	1.00	Roll	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	27-Jun-2016
14	11605002	16-Jun-2016	SER0000027	ADDITION PO.41504060 REPAIR WRAPPER ROLL ASS"Y DC#3 DWG.G53559	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	27-Jun-2016
15	11605072	16-Jun-2016	SER0000027	REPAIR HYD.CYL.1000-10404 AS SY DWG.M74650 FOR COIL OPENER SKM#2.	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	27-Jun-2016
16	11605073	16-Jun-2016	SER0000027	REPAIR HYDRAULIC CYLINDER TYPE C80/45/700 P/N 6530124 FOR COIL OPENER SHL.	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	27-Jun-2016
17	11605218	18-Jun-2016	SER0000027	Grinding pre-flex work roll Dia.44.5x1981.2 mm. (Mat.SUJ2, Roll Profile : Flat, Dia. Minimum after grinding >42.5 mm.,Surface Hardness after grinding >58 HRC)	13.00	Roll	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	27-Jun-2016
18	11605219	18-Jun-2016	SER0000027	Grinding ANTI-CROSS BOW WORK ROLL (Bottom) Dia.76.2x1981.2 mm. (Mat.SUJ2, Roll Profile : Flat, Dia. Minimum after grinding >71.2 mm. ,Surface Hardness after grinding >58 HRC)	4.00	Roll	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	27-Jun-2016
19	11600446	14-Jun-2016	SER0000028	REPAIR MASTER DRIVE 22 KW 400V 6SE7024-7ED61-Z"SIEMENS"	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	27-Jun-2016
20	11602740	14-Jun-2016	SER0000028	OVERHAUL MOTOR ELECTRO HYDRAULIC TYPE ED23/5 380V.50Hz.S/N No.361504	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	27-Jun-2016
21	11603193	14-Jun-2016	SER0000028	OVERHAUL MOTOR AC. 40-380V 3.7KW 100-1075RPM B4R160M6 (B3) = 6 EA	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	27-Jun-2016
22	11603993	14-Jun-2016	SER0000028	OVERHAUL MOTOR AC. 40-380V 3.7KW 100-1075RPM B4R160M6 B3 (6 EA)	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	27-Jun-2016
23	11605004	17-Jun-2016	SER0000028	ADD PO. 41503549 REPAIR ELECTRONICA SANTERNO INVERTER TYPE "SINUS PENTA 0250"	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	27-Jun-2016
24	11603032	14-Jun-2016	SER0000020	ว่าจ้างซ่อมพื้นลาดคอนกรีต บริเวณฝั่งขายคาใต้ถนนNO.*2	1.00	JOB	JANTHAWEE, MISS JARIYAPORN	BSP	jariyapornja@ssi-steel.com	INCOMPLETE	27-Jun-2016
25	11603958	18-Jun-2016	SER0000027	ว่าจ้างซ่อม THREADING TABLE PO-LINE	1.00	JOB	JANTHAWEE, MISS JARIYAPORN	BSP	jariyapornja@ssi-steel.com	INCOMPLETE	27-Jun-2016
26	11605129	18-Jun-2016	SER0000027	ว่าจ้างทำ BUSHING คานหลัง DIA. OD80 X ID75 X80 MM. ผลิต Fantuzzi จำนวน 4 EA. MAT : SS400	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	27-Jun-2016