

PR Received dated 20 - 26 April 2015

Services & Others

Post Dated 27 April 2015

Serial	PR No.	Document Date	Item Code	PR Line Description	PR Qty	Unit	Buyer	Buyer site	EMAIL ADDRESS	PR Status	RFQ Closing Dated
1	11502550	22-Apr-2015	SER0000027	REPAIR BTM.LEVELLING ROLL MODIFY SHAFT DIA.80MM. COMP.SET SKM#2 (MMDDDD002644)	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	4-May-15
2	11502553	22-Apr-2015	SER0000027	REPAIR HYD.CYL. "REXROTH" CDT3MP1/63/45/740 FOR SK#3.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	4-May-15
3	11502554	22-Apr-2015	SER0000027	REPAIR WHEEL HUB FOR FRONT WHEEL P/N. GA9.452013 (MMDDDD004210) [FAN./NO.16]	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	4-May-15
4	11502556	22-Apr-2015	SER0000027	REPAIR PUMP GP-VANE P/N 9T6123 (NO.1) FOR KRESS.303	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	4-May-15
5	11502556	22-Apr-2015	SER0000027	REPAIR PUMP GP-VANE P/N 9T6123 (NO.2) FOR KRESS.302	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	4-May-15
6	11502557	22-Apr-2015	SER0000027	REPAIR HAND VALVE(MAIN DISTRI.) MODEL.349-9202-014 FOR [FAN./NO.5]	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	4-May-15
7	11502559	22-Apr-2015	SER0000027	REPAIR STEERING CYLINDER P/N 243070 (NO.7) FOR [FAN/NO.3]	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	4-May-15
8	11502560	22-Apr-2015	SER0000027	REPAIR SPINDLE P/N.2AC7.243054 MMDDDD004660 FOR [FAN/NO.3L]	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	4-May-15
9	11502560	22-Apr-2015	SER0000027	REPAIR SPINDLE P/N.2AC7.243054 MMDDDD004660 FOR [FAN/NO.3R]	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	4-May-15
10	11502564	22-Apr-2015	SER0000027	REPAIR SPINDLE P/N.AC7.268014 FOR [FAN/6]	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	4-May-15
11	11502566	22-Apr-2015	SER0000027	REPAIR STEERING CYLINDER P/N 2144.832501 (NO.1) FOR [FAN/1]	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	4-May-15
12	11502561	22-Apr-2015	SER0000027	REPAIR RADIATOR P/N.284700400 M523 (NO.13) FOR[FAN./2]	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	4-May-15
13	11502561	22-Apr-2015	SER0000027	REPAIR RADIATOR P/N.284700400 M523 (NO.15) FOR[FAN./14]	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	4-May-15
14	11502565	22-Apr-2015	SER0000027	REPAIR OIL COOLER FOR DIFF. H= 20"xW=25"xTH=3.5" (NO1.)FOR [FAN/7]	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	4-May-15
15	11502565	22-Apr-2015	SER0000027	REPAIR OIL COOLER FOR DIFF. H= 20"xW=25"xTH=3.5" (NO2.)FOR [FAN/1]	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	4-May-15