

Serial	PR No.	Document Date	Item Code	PR Line Description	PR Qty	Unit	Buyer	Buyer site	EMAIL ADDRESS	PR Status	RFQ Closing Dated
1	11506194	17-Aug-2015	SER0000027	ว่าจ้าง Milling face cover shim thickness 150 to 105 MM for Back Up Roll ROM	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
2	11506446	18-Aug-2015	SER0000027	REPAIR SCRAP CHOPPER HEAD ASS-Y (R.H) (6.5MM) DWG.610026 POS.1-53 FOR SCRAP CHOPPER PO-LINE.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
3	11506447	18-Aug-2015	SER0000027	REPAIR SCRAP CHOPPER HEAD ASS-Y (L.H) (6.5MM) DWG.610024 POS.1-53 FOR SCRAP CHOPPER PO-LINE	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
4	11506448	18-Aug-2015	SER0000027	REPAIR HYD.CYL.PARKER 4.00DD2H-LRS-24M78" FOR PUSHER PLATE RE-COILER PO-LINE.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
5	11506449	18-Aug-2015	SER0000027	REPAIR HYD.CYL.PARKER 4.00 H2H-LR-34M3.5" FOR PINCH ROLL#2 PO-LINE.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
6	11506450	18-Aug-2015	SER0000027	REPAIR HYD.CYL PARKER 8C3H-KR 19 M12" FOR UNCOILER IN-OUT PO-LINE.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
7	11506451	18-Aug-2015	SER0000027	REPAIR SINGLE ROW STITCHER COMPLETE SET FOR PO-LINE.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
8	11506452	18-Aug-2015	SER0000027	REPAIR HYDRAULIC CYLINDER 254-C-JB-2H-R-1-4-M-C1200 DWG.15022002 FOR LOAD CAR SHL.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
9	11506453	18-Aug-2015	SER0000027	REPAIR CLAMP SEGMENT LOWER PART B/74390+TONGUE D/74394 FOR TENSION REEL SKM#1,2	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
10	11506454	18-Aug-2015	SER0000027	REPAIR ANTI COIL BREAK ROLLER COMPLETE SET DWG.M74777 FOR SKM#1,2	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
11	11506455	18-Aug-2015	SER0000027	REPAIR CLAMP SEGMENT UPPER PART A/74390 FOR TENSION REEL SKM#1,2	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
12	11506457	18-Aug-2015	SER0000027	REPAIR TONG STRUCTURE 107186(MMDD004541) FOR KRESS.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
13	11506502	19-Aug-2015	SER0000027	Repair Morgoil sleeve	5.00	Each	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
14	11506527	19-Aug-2015	SER0000027	Repair ฝัก Clamp Chock Bur. Rm. No. 5	1.00	Each	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
15	11506529	19-Aug-2015	SER0000027	MODIFY ROLL SLEEVE F4 KOPFLEX TO MAINA FOR PUT NEW WEAR PLATE& FLAT	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
16	11506571	20-Aug-2015	SER0000027	ว่าจ้างทำ Key bending Gap CB+หลังจากรัน Gear coupling screw jack RM	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
17	11506598	20-Aug-2015	SER0000027	REPAIR MECH.SEAL FFET1000-A3CE U004-SIZE100 (FLEXIBOX) NO.1	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
18	11506598	20-Aug-2015	SER0000027	REPAIR MECH.SEAL FFET1000-A3CE U004-SIZE100 (FLEXIBOX) NO.2	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
19	11506605	20-Aug-2015	SER0000027	ว่าจ้างเปลี่ยน Mech Seal Descaling Pump 1 NON-DRIVE	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
20	11506677	21-Aug-2015	SER0000027	REPAIR CONNECTOR DWG.G05641 POS.3(G04489) WITH PIN+PLATE LOCK COMPLETE SET	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
21	11506679	21-Aug-2015	SER0000027	REPAIR HYD.CYL.1000-10408 M/74823 FOR CROP SHEAR SKM#1,2 (NO.1)	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
22	11506679	21-Aug-2015	SER0000027	REPAIR HYD.CYL.1000-10408 M/74823 FOR CROP SHEAR SKM#1,2 (NO.2)	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
23	11506680	21-Aug-2015	SER0000027	REPAIR HYD.CYL.1000-10412 M/74715 COMPLETE WITH CLEVIS FOR END SUPPORT ARM OF TENSION REEL SKM#1,2	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
24	11506681	21-Aug-2015	SER0000027	REPAIR HYD.CYL. "REXROTH" CDT3MT4/80/56/800 HDM FOR BACK TENSION PINCH ROL SKM#3	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
25	11506682	21-Aug-2015	SER0000027	REPAIR HYD. BENDING STAND SKM#1 M74599 ASS-Y COMPLETE SET	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
26	11506683	21-Aug-2015	SER0000027	REPAIR EXIT STRAIGHTENER ROLL TOP NO.2,3 DWG.A108458 COMP SET FOR SKM#3	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
27	11506684	21-Aug-2015	SER0000027	REPAIR HEAT EXCHANGER PBG13SL-3PU-1-1 PO-LINE	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15

Serial	PR No.	Document Date	Item Code	PR Line Description	PR Qty	Unit	Buyer	Buyer site	EMAIL ADDRESS	PR Status	RFQ Closing Dated
28	11506685	21-Aug-2015	SER0000027	REPAIR TONG MOUTING STRUCTURE P/N 124952 FOR KRESS (K301)	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
29	11506687	21-Aug-2015	SER0000027	REPAIR TILT CYLINDER P/N 2144.836001(BORE = 170/ ROD = 80 / St. = 300MM.) [NO.19] FOR FANTUZZI	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
30	11506688	21-Aug-2015	SER0000027	REPAIR STEERING CYLINDER P/N 243070 (NO.13) FOR FANTUZZI	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
31	11506688	21-Aug-2015	SER0000027	REPAIR STEERING CYLINDER P/N 243070 (NO.15) FOR FANTUZZI	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
32	11506693	21-Aug-2015	SER0000027	REPAIR VALVE QUICK LIFT 8AP1-8D1-6Y1(69020) [NO.1] FOR KRESS	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
33	11506695	21-Aug-2015	SER0000027	REPAIR HYDRAULIC CYLINDER B100-70/300ST (WEIGHT SCALE) [NO.7]	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
34	11506696	21-Aug-2015	SER0000027	REPAIR HYDRAULIC CYLINDER B100-70/300ST (WEIGHT SCALE) [NO.2]	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
35	11506697	21-Aug-2015	SER0000027	REPAIR HYD.CYL.1000-10284 S87703/(UPPER WR CLAMP F4-F7) COMPLETE SET[NO.5]	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
36	11506698	21-Aug-2015	SER0000027	REPAIR HYD.CYL.1000-10285 [NO.5] FOR WR.CLAMP FIM.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
37	11506699	21-Aug-2015	SER0000027	REPAIR HYD.CYL.1000-10286 [NO.6] SIDE GUIDE FIM.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
38	11506700	21-Aug-2015	SER0000027	REPAIR LIFTING CYLINDER P/N 2144.831526 (LENGTH2140MM) [NO.19] USE FOR FANTUZZI	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
39	11506701	21-Aug-2015	SER0000027	REPAIR LIFTING CYLINDER P/N 2144.831526 (LENGTH2140MM) [NO.24] USE FOR FANTUZZI	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
40	11506702	21-Aug-2015	SER0000027	REPAIR LIFTING CYLINDER P/N 2144.831526 (LENGTH2140MM) [NO.30] USE FOR FANTUZZI	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
41	11506703	21-Aug-2015	SER0000027	REPAIR HYD.CYL 63/45/150 [NO.1] FOR ENTRY GATE DC#1-2	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	<a href="mailto:AekS@ssi-steel.com">AekS@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
42	11506603	20-Aug-2015	SER0000013	ว่าจ้างจัดหาเครื่องขอม Yard วันละ 8 ชม 2 วัน ประจำเดือน สิงหาคม 2558	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	<a href="mailto:Anchalee@ssi-steel.com">Anchalee@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
43	11506575	19-Aug-2015	SER0000020	ว่าจ้างรถไถคันดินได้ครนเบอร์ 2 3 ออกไว้ภายนอก จำนวน 2 ช.ม.	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	<a href="mailto:Anchalee@ssi-steel.com">Anchalee@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
44	11506442	20-Aug-2015	SER0000030	ซ่อมแซม Support ติดตั้งอุปกรณ์ และทอร์ควายสย สัญญาณสัญญาณ Level Transmitter and Level Switch Furnance 1,2 tank cooling System	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	<a href="mailto:Anchalee@ssi-steel.com">Anchalee@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
45	11506628	20-Aug-2015	SER9999999	ว่าจ้างออกแบบสถานีบริการจ่ายน้ำมัน D02 = 1 JOB	1.00	Each	MRS. ANCHALEE PIKKANESUAN	BSP	<a href="mailto:Anchalee@ssi-steel.com">Anchalee@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
46	11506456	18-Aug-2015	SER0000027	REPAIR AIR MOTOR M40 P/N 082200 (S/M DC#1)	1.00	JOB	MR. EKKAPONG THONGDEE	BSP	<a href="mailto:EkkapongT@ssi-steel.com">EkkapongT@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
47	11506163	18-Aug-2015	SER0000028	REWIND MOTOR AC. 380V 110KW 1480RPM TYPE 315S4 (B35) S/N No.	1.00	JOB	MR. EKKAPONG THONGDEE	BSP	<a href="mailto:EkkapongT@ssi-steel.com">EkkapongT@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
48	11506165	18-Aug-2015	SER0000028	OVERHAUL MOTOR AC. 380V 110KW 1480RPM TYPE 315S4 (B35) S/N No.	1.00	JOB	MR. EKKAPONG THONGDEE	BSP	<a href="mailto:EkkapongT@ssi-steel.com">EkkapongT@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
49	11506406	18-Aug-2015	SER0000028	OVERHAUL MOTOR DC TYPE 1GG3228-ONE40-1VV3-Z 181KW 420V 470A 1170-1350 RPM S/N No.1120423010001	1.00	JOB	MR. EKKAPONG THONGDEE	BSP	<a href="mailto:EkkapongT@ssi-steel.com">EkkapongT@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
50	11506490	19-Aug-2015	SER0000028	OVERHAUL MOTOR AC. 380V 110KW 1480RPM TYPE 315S4 (B35) S/N No.	1.00	JOB	MR. EKKAPONG THONGDEE	BSP	<a href="mailto:EkkapongT@ssi-steel.com">EkkapongT@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
51	11506517	19-Aug-2015	SER0000028	OVERHAUL MOTOR AC. 40-380V 3.7KW 100-1075RPM B4R160M6 (B3) = 12 EA FOR 2st AUG. 15 SD HSM	1.00	JOB	MR. EKKAPONG THONGDEE	BSP	<a href="mailto:EkkapongT@ssi-steel.com">EkkapongT@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
52	11506520	19-Aug-2015	SER0000028	ADD. PR.11506517 OVERHAUL MOTOR AC. 40-380V 3.7KW 100-1075RPM B4R160M6 (B3) = 12 EA FOR 2st AUG. 15 SD HSM	1.00	JOB	MR. EKKAPONG THONGDEE	BSP	<a href="mailto:EkkapongT@ssi-steel.com">EkkapongT@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
53	11506531	19-Aug-2015	SER0000028	OVERHAUL FAN VENTILATION MOD B35/1+AC.MOTOR 380V 1.5KW 50HZ	1.00	JOB	MR. EKKAPONG THONGDEE	BSP	<a href="mailto:EkkapongT@ssi-steel.com">EkkapongT@ssi-steel.com</a>	INCOMPLETE	31-Aug-15

Serial	PR No.	Document Date	Item Code	PR Line Description	PR Qty	Unit	Buyer	Buyer site	EMAIL ADDRESS	PR Status	RFQ Closing Dated
54	11504820	22-Aug-2015	SER0000027	REPAIR SERVO VALVE TYPE D765-1081-4 S19JOGBEVSXO (MOOG) [S/N.-D127]	1.00	JOB	MR. PATIYUTH DECHPICHAI	BKK	<a href="mailto:PatiyuthD@ssi-steel.com">PatiyuthD@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
55	11504821	22-Aug-2015	SER0000027	REPAIR SERVO VALVE TYPE D765-1081-4 S19JOGBEVSXO (MOOG) [S/N.-D130]	1.00	JOB	MR. PATIYUTH DECHPICHAI	BKK	<a href="mailto:PatiyuthD@ssi-steel.com">PatiyuthD@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
56	11506140	22-Aug-2015	SER0000027	REPAIR PROPORTIONAL VALVES D651-308A P70FBM 2CNFA [S/N.D146]	1.00	JOB	MR. PATIYUTH DECHPICHAI	BKK	<a href="mailto:PatiyuthD@ssi-steel.com">PatiyuthD@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
57	11506142	22-Aug-2015	SER0000027	REPAIR PROPORTIONAL VALVES TYPE D651-308D U70FQEBN6AOM [S/N.D163]	1.00	JOB	MR. PATIYUTH DECHPICHAI	BKK	<a href="mailto:PatiyuthD@ssi-steel.com">PatiyuthD@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
58	11506143	22-Aug-2015	SER0000027	REPAIR SERVO VALVE TYPE D791-5023 S25JQO6USXO-P (MOOG) W32365 [MAIN D.108 / PILOT D.117]	1.00	JOB	MR. PATIYUTH DECHPICHAI	BKK	<a href="mailto:PatiyuthD@ssi-steel.com">PatiyuthD@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
59	11506678	21-Aug-2015	SER0000026	ว่าจ้างซ่อม ELECTRODE WELDING MACHINE 220V 150A TRANSPOCKET 1500 "FRONIUS"	1.00	JOB	MR. PHAIBOON ONCHAWIANG	BSP	<a href="mailto:PhaiboonO@ssi-steel.com">PhaiboonO@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
60	11506395	21-Aug-2015	SER0000027	ว่าจ้างตรวจเช็คและประกอบแผ่นค้ำขาขี้น้ำมันไฮดรอลิคส์รถ Mobile crane KATO NO.2	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	<a href="mailto:phonnapatsa@ssi-steel.com">phonnapatsa@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
61	11506632	21-Aug-2015	SER0000027	ว่าจ้างตรวจเช็คและซ่อมถังน้ำมันเชื้อเพลิงรถเทรลเลอร์	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	<a href="mailto:phonnapatsa@ssi-steel.com">phonnapatsa@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
62	11506686	21-Aug-2015	SER0000027	REPAIR AXLE HOUSING P/N AC6.243043 FOR FANTUZZI 1-8.	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	<a href="mailto:phonnapatsa@ssi-steel.com">phonnapatsa@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
63	11506689	21-Aug-2015	SER0000027	REPAIR WHEEL HUB P/N ADO.243030 (ORIGINAL ONLY) [NO.8] FOR FANTUZZI	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	<a href="mailto:phonnapatsa@ssi-steel.com">phonnapatsa@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
64	11506690	21-Aug-2015	SER0000027	REPAIR HYD.OIL COOLER SIZE 37"x25 1/2"x5 1/2" [No.3] FOR HYD SYSTEM OF FANTUZZI	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	<a href="mailto:phonnapatsa@ssi-steel.com">phonnapatsa@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
65	11506690	21-Aug-2015	SER0000027	REPAIR HYD.OIL COOLER SIZE 37"x25 1/2"x5 1/2" [No.4] FOR HYD SYSTEM OF FANTUZZI	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	<a href="mailto:phonnapatsa@ssi-steel.com">phonnapatsa@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
66	11506692	21-Aug-2015	SER0000027	REPAIR RADIATOR (COOLER) P/N.Z2050T FOR COOLING THE ENGINE CUMMINS.	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	<a href="mailto:phonnapatsa@ssi-steel.com">phonnapatsa@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
67	11506694	21-Aug-2015	SER0000027	REPAIR MOTOR ASS'Y STARTING POS.1 P/N.23300-96119 [NO.1]	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	<a href="mailto:phonnapatsa@ssi-steel.com">phonnapatsa@ssi-steel.com</a>	INCOMPLETE	31-Aug-15
68	11506694	21-Aug-2015	SER0000027	REPAIR MOTOR ASS'Y STARTING POS.1 P/N.23300-96119 [NO.2]	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	<a href="mailto:phonnapatsa@ssi-steel.com">phonnapatsa@ssi-steel.com</a>	INCOMPLETE	31-Aug-15