

Serial	PR No.	Document Date	Item Code	PR Line Description	PR Qty	Unit	Buyer	Buyer site	EMAIL ADDRESS	PR Status	RFQ Closing Dated
1	11505726	29-Jul-2015	SER0000027	REPAIR TOP BUR CHOCKS - ซ่อมหัวค้ำบน	4.00	Each	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
2	11505761	27-Jul-2015	SER0000027	REPAIR HORIZONTAL CENTRIFUGAL PUMP "KSB" ETACHROM NC 040-250 FOR EIH. COB.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
3	11505762	27-Jul-2015	SER0000027	REPAIR CRADLE ROLL ASSY. G08271 DWG. K-360141 [1.B] (NEED CHECK SHEET INSP)	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
4	11505763	27-Jul-2015	SER0000027	REPAIR BLOCK DWG.G05406 POS.16(S-82378) (NO.1) FOR CROP SHEAR.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
5	11505763	27-Jul-2015	SER0000027	REPAIR BLOCK DWG.G05406 POS.16(S-82378) (NO.2) FOR CROP SHEAR.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
6	11505763	27-Jul-2015	SER0000027	REPAIR BLOCK DWG.G05406 POS.16(S-82378) (NO.3) FOR CROP SHEAR.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
7	11505763	27-Jul-2015	SER0000027	REPAIR BLOCK DWG.G05406 POS.16(S-82378) (NO.4) FOR CROP SHEAR.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
8	11505763	27-Jul-2015	SER0000027	REPAIR BLOCK DWG.G05406 POS.16(S-82378) (NO.5) FOR CROP SHEAR.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
9	11505764	27-Jul-2015	SER0000027	REPAIR BLOCK DWG.G05406 POS.17(S-82377) [NO.1] FOR CROP SHEAR.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
10	11505764	27-Jul-2015	SER0000027	REPAIR BLOCK DWG.G05406 POS.17(S-82377) [NO.2] FOR CROP SHEAR.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
11	11505764	27-Jul-2015	SER0000027	REPAIR BLOCK DWG.G05406 POS.17(S-82377) [NO.3] FOR CROP SHEAR.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
12	11505764	27-Jul-2015	SER0000027	REPAIR BLOCK DWG.G05406 POS.17(S-82377) [NO.4] FOR CROP SHEAR.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
13	11505766	27-Jul-2015	SER0000027	REPAIR BLOCK DWG.G05406 POS.18(S-82374)[NO.1] FOR CROP SHEAR.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
14	11505766	27-Jul-2015	SER0000027	REPAIR BLOCK DWG.G05406 POS.18(S-82374)[NO.2] FOR CROP SHEAR.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
15	11505766	27-Jul-2015	SER0000027	REPAIR BLOCK DWG.G05406 POS.18(S-82374)[NO.3] FOR CROP SHEAR.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
16	11505766	27-Jul-2015	SER0000027	REPAIR BLOCK DWG.G05406 POS.18(S-82374)[NO.4] FOR CROP SHEAR.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
17	11505766	27-Jul-2015	SER0000027	REPAIR BLOCK DWG.G05406 POS.18(S-82374)[NO.5] FOR CROP SHEAR.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
18	11505767	27-Jul-2015	SER0000027	REPAIR HYD. BENDING STAND SKM#1,2 M74599 ASS-Y COMPLETE SET.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
19	11505768	27-Jul-2015	SER0000027	REPAIR HYD.CYL.1000-10605 360175A (FOSSA / NO.3) [NEED CHECK SHEET INSP]	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
20	11505938	5-Aug-2015	SER0000027	REPAIR HYD.CYL.1000-10286 (NO.7) FOR SIDE GUIDE OPENING FIM.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
21	11505939	5-Aug-2015	SER0000027	REPAIR HYD.CYL.1000-10286 (NO.8) FOR SIDE GUIDE OPENING FIM.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
22	11505940	5-Aug-2015	SER0000027	REPAIR BODY(BY-PASS) DWG.W26872 POS.9 FOR WTP.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
23	11505942	5-Aug-2015	SER0000027	REPAIR HYD.CYL.1000-15969 DWG.G53722 (NO.4) FOR PULL BACK DC.1	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15

24	11505943	5-Aug-2015	SER0000027	REPAIR HYD.CYL.1000-10609 360175E (FOSSA) [Z12186-03]	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
25	11505944	5-Aug-2015	SER0000027	REPAIR HYD.CYL.FOR LIFTING CYL(H11) B250 R180 S1213 mm. FUR#3 (NO.2)	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
26	11505945	7-Aug-2015	SER0000027	REPAIR TRAVELLING WHEEL BRIDGE COMPLETE SET (DWG.MMDD006445) FOR OHC# 5,6,7,8,9	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
27	11505946	7-Aug-2015	SER0000027	GRINDING ANTI COIL BREAK ROLLER COMPLETE SET DWG.M74777 FOR SKM#1,2	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
28	11506023	6-Aug-2015	SER0000027	ว่าจ้างทำ cylinder crop shear (2 EA) และ rod crop shear (2 EA) ตามแบบแนบ	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
29	11506071	7-Aug-2015	SER0000027	REPAIR HYD.CYL.(FOSSA)1000-10608+1000-10611 ASS'Y COMPLETE SET WITH CLEVIS (BOTH SIDE) FOR TUCK-IN ARM.	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
30	11506073	6-Aug-2015	SER0000027	REPAIR DRIVE WHEEL DWG.003672 OHC.COMPLETE SET FOR OHC# 13,14 (NO.1)	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
31	11506073	6-Aug-2015	SER0000027	REPAIR DRIVE WHEEL DWG.003672 OHC.COMPLETE SET FOR OHC# 13,14 (NO.2)	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
32	11506099	7-Aug-2015	SER0000027	REPAIR IDLE ROLL UNLOAD CAR SKM#1,3 M74521 REV.D COMPLETE SET (NO.1)	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
33	11506099	7-Aug-2015	SER0000027	REPAIR IDLE ROLL UNLOAD CAR SKM#1,3 M74521 REV.D COMPLETE SET (NO.2)	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
34	11506099	7-Aug-2015	SER0000027	REPAIR IDLE ROLL UNLOAD CAR SKM#1,3 M74521 REV.D COMPLETE SET (NO.3)	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
35	11506099	7-Aug-2015	SER0000027	REPAIR IDLE ROLL UNLOAD CAR SKM#1,3 M74521 REV.D COMPLETE SET (NO.4)	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
36	11506100	7-Aug-2015	SER0000027	REPAIR HYD.CYL."REXROTH"CDT3 63 F11 HUM FOR W/R CLAMP SKM#1,2	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
37	11506101	7-Aug-2015	SER0000027	ว่าจ้างซ่อม Spent Acid Transfer Pump WERTNERT - NEPO-50-32-250 เนื่องจาก Shaft แตก และมีเสียงดังที่ Shaft ขณะใช้งาน	1.00	Each	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
38	11506102	7-Aug-2015	SER0000027	REPAIR HYDRAULIC CYLINDER 82.6-C-J-2H-R-1-4M-C- 120 WITH RACK FOR TOP ENTRY PINCH ROLL SHL#1	1.00	JOB	MR. AEK SIRIMUANGKHALA	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Aug-15
39	11505708	28-Jul-2015	SER0000012	ว่าจ้างรื้อ Mill Scale พร้อมอุปกรณ์ จำนวน 20,000 Tons.	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	17-Aug-15
40	11505790	28-Jul-2015	SER0000012	ว่าจ้างขุดลอกร่องระบายน้ำ	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	17-Aug-15
41	11505964	3-Aug-2015	SER0000013	Man power remove scale จำนวน 30 คน ตั้งแต่ วันที่ 25 กค.58-วันที่ 01 สค.58 ตั้งแต่เวลา 08.00-20.00น. พร้อมอุปกรณ์ PPF	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	17-Aug-15
42	11505967	5-Aug-2015	SER0000013	ว่าจ้างปาดครด ประจำเดือน ส.ค.2558 - ก.พ.2559	1,700,000.00	Kilograms	MRS. ANCHALEE PIKKANESUAN	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	17-Aug-15
43	11506038	6-Aug-2015	SER0000013	ว่าจ้างเช่ารถแบคโฮเพื่องานรวมกองสเกลประจำเดือน กค 58 จำนวน 2 วัน	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	17-Aug-15
44	11506091	8-Aug-2015	SER0000013	เช่ารถ Back hole ขุดดินเพื่อซ่อมท่อ Main Fur1+2 เวลา 2 วัน	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	17-Aug-15
45	11505859	3-Aug-2015	SER0000016	ว่าจ้างติดตั้งลิ้นกรองแสง 16 ตรม ที่ห้อง computer room ชั้น 2	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	17-Aug-15
46	11505858	3-Aug-2015	SER0000017	ว่าจ้างเปลี่ยนแผ่นหลังคาบริเวณ FUR จำนวน 756 ตรม	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	17-Aug-15
47	11506064	7-Aug-2015	SER0000017	ว่าจ้างเปลี่ยนหลังคาโดมที่ PO LINE	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	17-Aug-15
48	11505671	27-Jul-2015	SER0000020	ว่าจ้างรถไถ เพื่อทำการคันเศษดินโคลน ที่อุโมงบริเวณใต้คอนกรีตเบอร์ 2,3 ออกไปกำจัด เพื่อความสะอาด และสุขภาพพนักงาน จำนวน 1 JOB	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	17-Aug-15

49	11505879	3-Aug-2015	SER0000020	ขุดลอกดินโคลนช่อง Manhole และขุดลอกดินโคลนร่องระบายน้ำทางเข้า Internal Slab yard ระยะ 30 เมตร ด้าน OHC #2	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	17-Aug-15
50	11505881	3-Aug-2015	SER0000020	ขุดลอกดินโคลนช่อง Manhole ถนนเมน และขุดลอกดินโคลนร่องระบายน้ำทางเข้า Internal Slab yard ระยะ 45 เมตร ด้าน OHC.#3	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	17-Aug-15
51	11505784	28-Jul-2015	SER0000026	ว่าจ้างสอบเทียบ Digital multimeter fluke	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	17-Aug-15
52	11506066	6-Aug-2015	SER0000027	ว่าจ้างตัด Rack for เครื่องขุดฝุ่น Recuperator furnace 1 จำนวน 2 EA MMD/RO1/JULY15/14	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	17-Aug-15
53	11506092	8-Aug-2015	SER0000027	ว่าจ้างซ่อมหม้อน้ำ Make Up ที่ SK.3	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	17-Aug-15
54	11506074	7-Aug-2015	SER0000030	Calibration Flow Transmitter 1 ตัว (สอบเทียบหน่วยงาน)	1.00	Each	MRS. ANCHALEE PIKKANESUAN	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	17-Aug-15
55	11505935	3-Aug-2015	SER9999999	ค่าที่ปรึกษาด้านวิศวกรรม	1.00	JOB	MRS. ANCHALEE PIKKANESUAN	BSP	AnchaleeJ@ssi-steel.com	INCOMPLETE	17-Aug-15
56	11506045	8-Aug-2015	SER0000013	ตรวจเช็ค/ซ่อมแซม/เปลี่ยนอะไหล่/ เครื่อง Time Recorder	1.00	JOB	MRS. CHUTIPA TEANGTUNG	BSP	ChutipaT@ssi-steel.com	INCOMPLETE	17-Aug-15
57	11505770	27-Jul-2015	SER0000028	OVERHAUL MOTOR ELECTRO HYDRAULIC TYPE ED301/6 380V 50Hz FOR HOIST OHC.2,3 Sr.No. 92-36373	1.00	JOB	MR. EKKAPONG THONGDEE	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Aug-15
58	11505771	3-Aug-2015	SER0000028	REPAIR DRIVE FOR X,Z AXIS G/M#2 DK02.3-100-7-FW P/N279430 Sr.No. 283414-36241	1.00	JOB	MR. EKKAPONG THONGDEE	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Aug-15
59	11505772	27-Jul-2015	SER0000028	OVERHAUL MOTOR AC. 380V 55/63KW 2950RPM M250M2"FIMET"(B3) S/N No.212230404	1.00	JOB	MR. EKKAPONG THONGDEE	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Aug-15
60	11505786	3-Aug-2015	SER0000028	MAKE LOWER POLE COVER(CASING) MAT=304L	1.00	JOB	MR. EKKAPONG THONGDEE	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Aug-15
61	11505788	3-Aug-2015	SER0000028	MAKE UPPER POLE COVER(CASING) MAT=304L	1.00	JOB	MR. EKKAPONG THONGDEE	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Aug-15
62	11505815	3-Aug-2015	SER0000028	OVERHAUL MOTOR DC. 47 KW 295 V 328 RPM TYPE MDT 812 D2 S/N No.184432	1.00	JOB	MR. EKKAPONG THONGDEE	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Aug-15
63	11505816	3-Aug-2015	SER0000028	OVERHAUL MOTOR DC. 47 KW 295 V 328 RPM TYPE MDT 812 D2 S/N No.184367	1.00	JOB	MR. EKKAPONG THONGDEE	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Aug-15
64	11505970	6-Aug-2015	SER0000028	OVERHAUL MOTOR AC. 6.6KV 520KW 1480RPM Type CTV400V4 S/N No.64852 (EMD/PAD/JUL15/001)	1.00	JOB	MR. EKKAPONG THONGDEE	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Aug-15
65	11506048	6-Aug-2015	SER0000028	HYDROSTATIC TEST TANK HEATER BASE HEATER FUR3 No.1 (20 BAR)	1.00	JOB	MR. EKKAPONG THONGDEE	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Aug-15
66	11506051	6-Aug-2015	SER0000028	OVERHAUL MOTOR AC 6.6KV 2850KW 287.1A 1485RPM B3 "ANSALDO" TYPE CT 630X4 FOR DESCALING PUMP S/N No.64350	1.00	JOB	MR. EKKAPONG THONGDEE	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Aug-15
67	11506077	7-Aug-2015	SER0000028	สั่งทำชุดยึด Cable track EIH	1.00	Set	MR. EKKAPONG THONGDEE	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Aug-15
68	11505849	3-Aug-2015	SER9999999	โต๊ะจีนจำนวน 60 ตัว เก้าอี้ จำนวน 200 พร้อมผ้าปูโต๊ะพร้อมทั้งจัดโต๊ะให้เรียบร้อย	60.00	Each	MISS JARIYAPORN JANTHAWEE	BSP	jariyapornja@ssi-steel.com	INCOMPLETE	17-Aug-15
69	11506028	4-Aug-2015	SER0000013	ตรวจวัดสภาพแวดล้อมในการทำงาน (เสียง) ปี 2558 (ซ้ำ)	1.00	JOB	MRS. MONTHA CHUMBOON	BSP	MonthaA@ssi-steel.com	INCOMPLETE	17-Aug-15
70	11505848	3-Aug-2015	SER9999999	ป้ายไววัล ขนาด 1.5*3 เมตร	3.00	Each	MRS. MONTHA CHUMBOON	BSP	MonthaA@ssi-steel.com	INCOMPLETE	17-Aug-15
71	11506029	4-Aug-2015	SER9999999	ป้ายความปลอดภัย (ป้ายเตือนความสูง)	1.00	JOB	MRS. MONTHA CHUMBOON	BSP	MonthaA@ssi-steel.com	INCOMPLETE	17-Aug-15
72	11505783	28-Jul-2015	SER0000026	ว่าจ้างซ่อมเครื่องเจียรคยยาว รุ่น GGS 27L "BOSCH" FIX3000890	1.00	JOB	MR. PHAIBOON ONCHAWIANG	BSP	Phai boonO@ssi-steel.com	INCOMPLETE	17-Aug-15
73	11505722	27-Jul-2015	SER0000027	ว่าจ้างซ่อมชุดหัวตัดแก๊ส " HARRIS" MODEL 62-5F จำนวน 3 EA	1.00	JOB	MR. PHAIBOON ONCHAWIANG	BSP	Phai boonO@ssi-steel.com	INCOMPLETE	17-Aug-15

74	11505851	3-Aug-2015	SER0000027	ว่าจ้างตรวจเช็คและซ่อมเครื่องฉีดน้ำแรงดันสูง รุ่น ZAPHIR-DST	1.00	JOB	MR. PHAIBOON ONCHAWIANG	BSP	PhaiboonO@ssi-steel.com	INCOMPLETE	17-Aug-15
75	11505933	7-Aug-2015	SER0000026	ว่าจ้างตรวจเช็คและซ่อมระบบเบรครถดีมพ์บรรทุกสเกลหัวแดง	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	17-Aug-15
76	11505934	7-Aug-2015	SER0000026	ว่าจ้างตรวจเช็คและซ่อมระบบเกียร์หมุนน้ำมันไฮดรอลิคสกรบรถทุกคิด เครนเบอร์ 3	1.00	JOB	MISS PHONNAPAT SAKHAN	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	17-Aug-15
77	11505797	7-Aug-2015	SER0000013	stamp ชื่อภาษาไทย, Stamp ชื่อภาษาอังกฤษ, Stamp ลายเซ็นดี อย่างละ 1 อัน	3.00	Each	MISS PITTAYARAT PHUENPHA	BSP	pittayaratph@ssi-steel.com	INCOMPLETE	17-Aug-15