

PR Received dated 3 OCT 2016 - 9 OCT 2016

Services & Others

Post Dated 10 OCT 2016

Serial	PR No.	Document Date	Item Code	PR Line Description	PR Qty	Unit	Buyer	Buyer site	EMAIL ADDRESS	PR Status	RFQ Closing Dated
1	11606480	5-Oct-2016	SER0000026	ว่าจ้างซ่อม HAND PUMP P-392 "ENERPAC" [S/N.7151200002]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Oct-2016
2	11606480	5-Oct-2016	SER0000026	ว่าจ้างซ่อม HAND PUMP P-392 "ENERPAC" [S/N.7151200128]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Oct-2016
3	11606480	5-Oct-2016	SER0000026	ว่าจ้างซ่อม HAND PUMP P-392 "ENERPAC" [S/N.7130400014]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Oct-2016
4	11606480	5-Oct-2016	SER0000026	ว่าจ้างซ่อม HAND PUMP P-392 "ENERPAC" [S/N.7130400013]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Oct-2016
5	11606480	5-Oct-2016	SER0000026	ว่าจ้างซ่อม HAND PUMP P-392 "ENERPAC" [S/N.1HY090107]	1.00	JOB	SIRIMUANGKHALA, MR. AEK	BSP	AekS@ssi-steel.com	INCOMPLETE	17-Oct-2016
6	11607260	6-Oct-2016	SER0000027	REPAIR BOTTOM STRIPPER WR R1 No.7 และ No.11	2.00	Each	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
7	11607572	6-Oct-2016	SER0000027	REPAIR CONNECTING PLATE DWG.G05074 POS.11(G01693) (NO1)	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
8	11607572	6-Oct-2016	SER0000027	REPAIR CONNECTING PLATE DWG.G05074 POS.11(G01693) (NO.2)	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
9	11607837	5-Oct-2016	SER0000027	REPAIR WRAPPER ROLL COMPLETE SET G05700 (SEE DETAIL) [WR1/DC2] (NEED CHECK SHEET INSP.)	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
10	11608769	3-Oct-2016	SER0000027	ADDITION PO.41604014 REPAIR MANDREL COMPLETESET AS SYM74449 1-4	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
11	11608874	3-Oct-2016	SER0000027	Re-lining Squeegee Roll Dia.255x2440 mm. (Mat.Neoprene, Roll Profile : Crown,Hardness 50 - 65 Shore A) จำนวน5 Rolls ไทเทค Roll No.5,10,23,27,40	5.00	Roll	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
12	11608987	7-Oct-2016	SER0000027	REPAIR HYD.CYL.PUSHER PLATE SK3.	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
13	11608988	7-Oct-2016	SER0000027	REPAIR HORIZONTAL CENTRIFUGAL PUMP CP001,CP002 (NP100-02)	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
14	11608989	7-Oct-2016	SER0000027	REPAIR HORIZONTAL CENTRIFUGAL PUMP CP001,CP002 (NP100-04)	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
15	11608990	7-Oct-2016	SER0000027	REPAIR SET GASKET CLY.CODE 23044008001(NO.01)	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
16	11608991	7-Oct-2016	SER0000027	REPAIR REDUCTION GEAR#DET.UAA018MOD.K2VK-200 "SPIG" (NO.5)	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
17	11608992	8-Oct-2016	SER0000027	REPAIR CRADLE G05636 POS.2-10,12,14-16 COMPLETE SET ASS-Y (F3)	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
18	11608994	8-Oct-2016	SER0000027	REPAIR RAIL (AS SY G05483 POS.6) G04448 FOR F3.	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
19	11608995	8-Oct-2016	SER0000027	REPAIR RAIL (AS SY G05483 POS.7) G04449 FOR F3.	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
20	11608996	8-Oct-2016	SER0000027	REPAIR SLIDE BACK UP ROLL COMP.SET(RM G05276 POS.3-6) OR (FM G05641 POS.8-11)	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
21	11608997	8-Oct-2016	SER0000027	REPAIR CONNECTOR DWG.G05641 POS.3(G04489) WITH PIN+PLATE LOCK COMPLETE SET	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
22	11608998	8-Oct-2016	SER0000027	REPAIR GUIDE COMP.SET DWG.G53577 POS.1,5,6,14-28 ,32,DC [EXIT /DC.2]	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
23	11609000	8-Oct-2016	SER0000027	REPAIR TRANSFER CARS ASS Y G05726 2/2 (DC.2)	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
24	11609003	7-Oct-2016	SER0000027	REPAIR DESCALING VALVE 4" 2-WAY MOD.4108A P/N 97933941(NO.8/9) [NEED CHECK SHEET INSP]	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
25	11609004	7-Oct-2016	SER0000027	REPAIR HYD.CYL.1000-10396 M74777 FOR ANTICOIL BREAK UP-DOWN SKM#1,2 (NO.1)	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
26	11609004	7-Oct-2016	SER0000027	REPAIR HYD.CYL.1000-10396 M74777 FOR ANTICOIL BREAK UP-DOWN SKM#1,2 (NO.2)	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
27	11609006	7-Oct-2016	SER0000027	REPAIR TOP LEVELLING ROLL COMPLETE SET POS.1-26 (MODIFY) DWG.MMDD004136 SHL	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
28	11609011	7-Oct-2016	SER0000027	REPAIR DESCALING VALVE "INOXHP" MODEL:VPZ09MLANC11EA(6/6)	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
29	11603114	6-Oct-2016	SER0000028	OVERHAUL MOTOR DC. 1000KW 700V 300/800RPM DH710X49EC2SP S/N No.184342	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
30	11607364	3-Oct-2016	SER0000028	REWINDING MOTOR AC.380V.250KW.1490RPM.TYPE M2CA355MA-4(B3) S/N.3266053	1.00	JOB	THONGDEE, MR. EKKAPONG	BSP	EkkapongT@ssi-steel.com	INCOMPLETE	17-Oct-2016
31	11608795	3-Oct-2016	SER0000012	เช่ารถ back hole ขุดดินเพื่อเปลี่ยนท่อสำหรับส่งไปเดาเผาเหล็ก 1 วัน	1.00	JOB	JANTHAWEE, MISS JARIYAPORN	BSP	jariyapornja@ssi-steel.com	INCOMPLETE	17-Oct-2016
32	11608777	3-Oct-2016	SER0000020	ว่าจ้างเครื่องจักรทำการเกรด บด อัด ดิน พื้นผิววาง SLAB จำนวน 2 วัน	2.00	Days	JANTHAWEE, MISS JARIYAPORN	BSP	jariyapornja@ssi-steel.com	INCOMPLETE	17-Oct-2016

PR Received dated 3 OCT 2016 - 9 OCT 2016

Services & Others

Post Dated 10 OCT 2016

Serial	PR No.	Document Date	Item Code	PR Line Description	PR Qty	Unit	Buyer	Buyer site	EMAIL ADDRESS	PR Status	RFQ Closing Dated
33	11608975	7-Oct-2016	SER0000027	เช่ารถ back hole ขุดดิน เพื่อซ่อมท่อส่งน้ำ จากวังยาวข้างบ่อ TCRSS เวลา 2 วัน รายละเอียดตามเอกสารแนบ	1.00	JOB	JANTHAWEE, MISS JARIYAPORN	BSP	jariyapornja@ssi-steel.com	INCOMPLETE	17-Oct-2016
34	11608984	7-Oct-2016	SER0000027	REPAIR SPENT ACID BASKET STRAINER PO-LINE	1.00	JOB	JANTHAWEE, MISS JARIYAPORN	BSP	jariyapornja@ssi-steel.com	INCOMPLETE	17-Oct-2016
35	11608782	4-Oct-2016	SER0000027	จัดซื้อจัดหาวัสดุโครงการ 25 ปีเอสเอสไอ 250 ความดีพื้นดวงใจอาสา ความดีที่ 146 ปรับปรุงภูมิทัศน์และทำสีอาคารหลวงปู่ช่วง วัดหินกอง (ตามเอกสารแนบ)	1.00	JOB	CHUMBOON, MRS. MONTHA	BSP	MonthaA@ssi-steel.com	INCOMPLETE	17-Oct-2016
36	11608781	4-Oct-2016	SER0000026	จัดหาอะไหล่เพลาล้อด้านซ้ายรถดั้มท์สเกลหัวแดง	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	17-Oct-2016
37	11606057	6-Oct-2016	SER0000027	REPAIR WHEEL HUB FOR FRONT AXLE P/N.GA9.268030 (MMDDD004215) [NO.1] FOR FRONT WHEEL OF FANTUZZI	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	17-Oct-2016
38	11606057	6-Oct-2016	SER0000027	REPAIR WHEEL HUB FOR FRONT AXLE P/N.GA9.268030 (MMDDD004215) [NO.2] FOR FRONT WHEEL OF FANTUZZI	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	17-Oct-2016
39	11606061	5-Oct-2016	SER0000027	REPAIR HOIST CYLINDER P/N 078891 (LIFTING SYS) FOR KRESS.	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	17-Oct-2016
40	11606062	6-Oct-2016	SER0000027	REPAIR STEERING CYLINDER P/N 5J1326 FOR STEERING GROUP OF KRESS	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	17-Oct-2016
41	11606481	6-Oct-2016	SER0000027	REPAIR WHEEL STRUCTURE P/N 75268 FOR WHEEL AND TIRE OF KRESS	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	17-Oct-2016
42	11607565	6-Oct-2016	SER0000027	REPAIR HYDRAULIC GEAR PUMP MODEL P365PA01 (P/N 29860089) FOR FANTUZZI	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	17-Oct-2016
43	11609008	7-Oct-2016	SER0000027	REPAIR MOTOR ASS'Y STARTING POS.1 P/N.23300-96119 FOR VEH.	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	17-Oct-2016
44	11609009	7-Oct-2016	SER0000027	REPAIR MOTOR ASS'Y STARTING POS.1 P/N.23300-96119 (NO.2)	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	17-Oct-2016
45	11609010	7-Oct-2016	SER0000027	REPAIR MOTOR ASS'Y STARTING POS.1 P/N.23300-96119(NO.3)	1.00	JOB	SAKHAN, MISS PHONNAPAT	BSP	phonnapatsa@ssi-steel.com	INCOMPLETE	17-Oct-2016
46	11607836	3-Oct-2016	SER0000027	REPAIR PROPORTIONAL VALVES MODEL D651-307D TYPE U70FQEACN6AOM [S/N.D 153]	1.00	JOB	PHETPHO, MR. TANAPOL	BKK	tanapolp@ssi-steel.com	INCOMPLETE	17-Oct-2016